









### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |

شماره صفحه: 1 از 58

# طرح نگهداشت و افزایش تولید ۲۷ مخزن

### HAZOP REPORT FOR COMPRESSOR STATION

نگهداشت و افزایش تولید میدان نفتی بینک

| JUL. 2022 | IFI                     | A.Baghaei    | M.Fakharian | M.Mehrshad   |                 |
|-----------|-------------------------|--------------|-------------|--------------|-----------------|
| Date      | Purpose of Issue/Status | Prepared by: | Checked by: | Approved by: | CLIENT Approval |
| _         |                         |              |             |              |                 |

Class: 3 CLIENT Doc. Number: F0Z-708725

### Status:

IDC: Inter-Discipline Check
IFC: Issued For Comment
IFA: Issued For Approval
AFD: Approved For Design
AFC: Approved For Construction
AFP: Approved For Purchase
AFQ: Approved For Quotation
IFI: Issued For Information
AB-R: As-Built for CLIENT Review

AB-A: As-Built -Approved



· ۵۳ - · ۷۳ - 9 1 1 4

### نگهداشت و افزایش تولید میدان نفتی بینک سطح الارض







# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

HAZOP REPORT FOR COMPRESSOR STATION بسته کاری صادر کننده نوع مدرك رشته تسهيلات نسخه پروژه سريال GCS PEDCO D00 BK 120 GE RT 0004

شماره صفحه: 2 از 58

### **REVISION RECORD SHEET**

| PAGE          | D00                   | D01 | D02 | D03 | D04 |
|---------------|-----------------------|-----|-----|-----|-----|
| 1             | Х                     |     |     |     |     |
| 2             | X                     |     |     |     |     |
| 3             | X                     |     |     |     |     |
| 4             | X                     |     |     |     |     |
| 5             | X                     |     |     |     |     |
| <u>6</u>      | X                     |     |     |     |     |
| 7             | X                     |     |     |     |     |
| <u>8</u><br>9 | Ŷ                     |     |     |     |     |
| 10            | X                     |     |     |     |     |
| 11            | X                     |     |     |     |     |
| 12            | X                     |     |     |     |     |
| 13            | X                     |     |     |     |     |
| 14            | X                     |     |     |     |     |
| 15            | X                     |     |     |     |     |
| 16            | Χ                     |     |     |     |     |
| 17            | X                     |     |     |     |     |
| 18            | X                     |     |     |     |     |
| 19            | X                     |     |     |     |     |
| 20            | X                     |     |     |     |     |
| 21            | X                     |     |     |     |     |
| 22            | X                     |     |     |     |     |
| 23            | X                     |     |     |     |     |
| 24            | X                     |     |     |     |     |
| 25            | X                     |     |     |     |     |
| 26            | X                     |     |     |     |     |
| 27            | X                     |     |     |     |     |
| 28            | X                     |     |     |     |     |
| 29<br>30      | X                     |     |     |     |     |
| 31            | X                     |     |     |     |     |
| 32            | X                     |     |     |     |     |
| 33            | X                     |     |     |     |     |
| 34            | X                     |     |     |     |     |
| 35            | X                     |     |     |     |     |
| 36            | X                     |     |     |     |     |
| 37            | X                     |     |     |     |     |
| 38            | X                     |     |     |     |     |
| 39            | X                     |     |     |     |     |
| 40            | X                     |     |     |     |     |
| 41            | X                     |     |     |     |     |
| 42            | X                     |     |     |     |     |
| 43            | X                     |     |     |     |     |
| 44            | X                     |     |     |     |     |
| 45            | X                     |     |     |     | -   |
| 46            | X                     |     |     |     |     |
| 47            | X                     |     |     |     |     |
| 48            | X                     |     |     |     |     |
| 49<br>50      |                       |     |     |     |     |
| 51            | X<br>X<br>X<br>X<br>X |     |     |     |     |
| 52            | X                     |     |     | 1   |     |
| 53            | X                     |     |     |     |     |
| 54            | Х                     |     |     |     |     |
| 55            | X                     |     |     |     |     |
| 56            | X                     |     |     |     |     |
| 57            | X                     |     |     |     |     |
| 58            | X                     |     |     |     |     |
| 59            |                       |     |     |     |     |
| 60            |                       |     |     |     |     |
| 61            | 1                     |     |     |     |     |
| 62            | 1                     |     |     |     |     |
| 63            |                       |     |     |     |     |
| 64            | 1                     | l   |     | 1   | ı   |

| PAGE       | D00      | D01      | D02 | D03      | D04 |
|------------|----------|----------|-----|----------|-----|
| 66         |          |          |     |          |     |
| 67         |          |          |     |          |     |
| 68<br>69   |          |          |     |          |     |
| 70         |          |          |     |          |     |
| 71         |          |          |     |          |     |
| 72         |          |          |     |          |     |
| 73         |          |          |     |          |     |
| 74<br>75   |          |          |     |          |     |
| 76         |          |          |     |          |     |
| 77         |          |          |     |          |     |
| 78         |          |          |     |          |     |
| 79         |          |          |     |          |     |
| 80<br>81   |          |          |     |          |     |
| 82         |          |          |     |          |     |
| 83         |          |          |     |          |     |
| 84         |          |          |     |          |     |
| 85         |          |          |     |          |     |
| 86         |          |          |     |          |     |
| 87         |          |          |     |          |     |
| 88<br>89   |          |          |     |          |     |
| 90         |          |          |     |          |     |
| 91         |          |          |     |          |     |
| 92         |          |          |     |          |     |
| 93         |          |          |     |          |     |
| 94         |          |          |     |          |     |
| 95<br>96   |          |          |     |          |     |
| 96<br>97   |          |          |     |          |     |
| 98         |          |          |     |          |     |
| 99         |          |          |     |          |     |
| 100        |          |          |     |          |     |
| 101        |          |          |     |          |     |
| 102<br>103 |          |          |     |          |     |
| 104        |          |          |     |          |     |
| 105        |          |          |     |          |     |
| 106        |          |          |     |          |     |
| 107        | 1        |          |     |          |     |
| 108        |          |          |     |          |     |
| 109<br>110 |          |          |     |          |     |
| 111        |          |          |     |          |     |
| 112        |          |          |     |          |     |
| 113        |          |          |     |          |     |
| 114        | -        |          |     |          |     |
| 115<br>116 |          |          |     |          |     |
| 116<br>117 |          |          |     |          |     |
| 118        |          |          |     |          |     |
| 119        |          |          |     |          |     |
| 120        |          |          |     |          |     |
| 121        |          |          |     |          |     |
| 122        |          |          |     |          |     |
| 123<br>124 |          |          |     |          |     |
| 125        |          |          |     |          |     |
| 126        |          |          |     |          |     |
| 127        |          |          |     |          |     |
| 128        |          |          |     |          |     |
| 129        |          |          |     |          |     |
| 130        | <u> </u> | <u> </u> | L   | <u> </u> |     |



احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک









# شماره پیمان:

|       | پيسان.     | سارت |
|-------|------------|------|
| ۰۵۳ – | ٠٧٣ - ٩١٨۴ |      |

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |

شماره صفحه: 3 از 58

### **CONTENTS**

| 1.0        | INTRODUCTION                      | 4  |
|------------|-----------------------------------|----|
| 2.0        | SCOPE                             | 5  |
| 3.0        | NORMATIVE REFERENCES              | 5  |
| 3.1<br>3.2 | International Codes and Standards | 5  |
| 4.0        | PURPOSE                           | 5  |
| 5.0        | HAZOP STUDY OVERVIEW              | 5  |
| 6.0        | PROCEDURE                         | 6  |
| 7.0        | HAZOP OUTCOMES                    | 7  |
| 8.0        | ATTACHMENTS                       |    |
| 8.1        | Appendix A –Team Members          | 8  |
| 8.2        | Appendix B – Drawings List        | 10 |
| 8.3        | APPENDIX C – NODES LIST           | 11 |
| 8.4        | Appendix D – Recommendations List | 13 |
| 8.5        | APPENDIX E – HAZOP WORKSHEETS     | 19 |
| 8.6        | APPENDIX F – MARKED-UP P&IDS      | 58 |
|            |                                   |    |











### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

.04 - . 14 - 9114

|       | HAZOP REPORT FOR COMPRESSOR STATION |            |         |      |          |       |      |
|-------|-------------------------------------|------------|---------|------|----------|-------|------|
| پروژه | بسته کاری                           | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |
| BK    | GCS                                 | PEDCO      | 120     | GE   | RT       | 0004  | D00  |

شماره صفحه: 4 از 58

#### 1.0 INTRODUCTION

Binak oilfield in Bushehr province is a part of the southern oilfields of Iran, is located 20 km northwest of Genaveh city.

With the aim of increasing production of oil from Binak oilfield, an EPC/EPD Project has been defined by NIOC/NISOC and awarded to Petro Iran Development Company (PEDCO). Also, PEDCO (as General Contractor) has assigned the EPC-packages of the Project to "Hirgan Energy - Design and Inspection" JV.

As a part of the Project, a New Gas Compressor Station (adjacent to existing Binak GCS) shall be constructed to gather of 15 MMSCFD (approx.) associated gases and compress & transfer them to Siahmakan GIS.

### **GENERAL DEFINITION**

The following terms shall be used in this document.

CLIENT: National Iranian South Oilfields Company (NISOC)

PROJECT: Binak Oilfield Development – Surface Facilities; New

Gas Compressor Station

EPD/EPC CONTRACTOR (GC): Petro Iran Development Company (PEDCO)

EPC CONTRACTOR: Joint Venture of: Hirgan Energy – Design & Inspection

(D&I) Companies

VENDOR: The firm or person who will fabricate the equipment or

material.

EXECUTOR: Executor is the party which carries out all or part of

construction and/or commissioning for the project.

THIRD PARTY INSPECTOR (TPI): The firm appointed by EPD/EPC CONTRACTOR (GC)

and approved by CLIENT (in writing) for the inspection

of goods.

SHALL: Is used where a provision is mandatory.

SHOULD: Is used where a provision is advisory only.

WILL: Is normally used in connection with the action by

CLIENT rather than by an EPC/EPD CONTRACTOR,

supplier or VENDOR.

MAY: Is used where a provision is completely discretionary.













| ىيمان: | شماده |
|--------|-------|
| ييس.   | سسرت  |

.04 - . 14 - 9146

|       | HAZOP REPORT FOR COMPRESSOR STATION |            |         |      |          |       |      |
|-------|-------------------------------------|------------|---------|------|----------|-------|------|
| پروژه | بسته کاری                           | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |
| BK    | GCS                                 | PEDCO      | 120     | GE   | RT       | 0004  | D00  |

شماره صفحه: 5 از 58

#### 2.0 SCOPE

The scope of HAZOP study covers all P&IDs for New Gas Compressor Station. The list of P&IDs is presented in appendix B.

### 3.0 NORMATIVE REFERENCES

#### 3.1 INTERNATIONAL CODES AND STANDARDS

IEC 61882:2016 Hazard and Operability studies (HAZOP Studies) –
 Application guide

#### 3.2 THE PROJECT DOCUMENTS

BK-GNRAL-HD-000-PR-DB-0001-D05
 Process Basis of Design

BK-GCS-PEDCO-120-PR-BD-0001
 ESD Block Diagram

#### 4.0 PURPOSE

The purpose of this document is to provide the results of "HAZOP Study" for **Binak Oilfield Development – Surface Facilities; New Gas Compressor Station**.

The objective of HAZOP study is to perform and achieve the following tasks and goals as far as practicable given the latest piping and instrumentation diagrams (P&ID's) to identify any potential hazards associated with the system and its utility systems:

- To identify any potential operating difficulties,
- Examine the effectiveness of those measures already incorporated in the design to mitigate the frequency and/or consequences of such hazards;
- To raise action items for addressing those hazards that the present design does not satisfactorily address.

#### 5.0 HAZOP STUDY OVERVIEW

Meetings were conducted in 4 sessions from June 26 to 29, 2022 held in Neyshekar Hotel main meeting hall, Ahvaz.

A team comprising of experts from different disciplines of National Iranian South Oilfields Company (NISOC), Petro Iran Development Company (PEDCO) and Hirgan Energy Company conducted the study with a third-party HAZOP Chairman and Scribe. The list of team members is presented in appendix A.



### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک









شماره پیمان:

.04 - . 14 - 9114

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |

شماره صفحه: 6 از 58

#### 6.0 PROCEDURE

The review methodology will be the "Guide Word" HAZOP technique and will be performed in accordance with the guidelines published by the Center for Chemical Process Safety (CCPS) of the American Institute of Chemical Engineers (AIChE) and also noted in IEC 61882.

The purpose of the review should not be only to resolve the action items but also to identify credible deviations from the design intent. The method identifies hazards and postulates possible accident sequences resulting from such hazards; Innovative thinking then identifies the consequences of these scenarios. The process demonstrates to the Owner/Management that prudent steps which have been taken to provide a safe installation and operation.

The scope of the HAZOP shall be therefore, on identifying potential process hazards or operability concerns, not on finding solutions to reduce or eliminate these concerns. Attempting to solve problems by the HAZOP team can result in a long and inefficient study process. At the same time, the HAZOP study cannot be intended as a review of Project Design Basis and Operating Philosophies, since these must be considered as resolved when the HAZOP study will be carried out.

Each system or equipment should be divided into subsystems by consensus of the review team. The selected system shall be identified by a study node numbers and for easy reference a color code can also be inserted on the related P&ID prior to the review and worksheet during the review.

### List of possible parameters and guidewords

| Deviations               | Guide Word          | Parameter   |
|--------------------------|---------------------|-------------|
| No/Less Flow             | No/Less             | Flow        |
| More Flow                | More                | Flow        |
| Reverse/Misdirected Flow | Reverse/Misdirected | Flow        |
| High Temperature         | High                | Temperature |
| Low Temperature          | Low                 | Temperature |
| High Pressure            | High                | Pressure    |
| Low Pressure             | Low                 | Pressure    |
| High Level               | High                | Level       |
| Low Level                | Low                 | Level       |
| Maintenance Hazards      | Other than          | Maintenance |
| Leakage                  | As well as          | Flow        |
| Corrosion                | As well as          | Operation   |
| Composition              | As well as          | Composition |









### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

.04 - .14 - 114

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |  |  |

شماره صفحه: 7 از 58

| Deviations                | Guide Word | Parameter         |
|---------------------------|------------|-------------------|
| Start-up/Shutdown Hazards | Other than | Start-up/Shutdown |
| Loss of Utilities         | Other than | Operation         |
| Miscellaneous             | As well as | Operation         |

#### 7.0 HAZOP OUTCOMES

In order to facilitate the study, the process was broken down into 20 nodes. The node list is presented in appendix C. A total of 131 recommendations were obtained which are shown in appendix D. The recommendations are categorized in two groups, namely OPEN and CLOSED.

Closed recommendations are those that the team have arrived at a consensus that it is required to be done. 128 closed recommendation were obtained in the meetings. Open recommendations are those that need more information from vendor for the final decision. 3 open recommendations were proposed during the meetings.

Appendix E consists of detailed HAZOP Worksheets of the study.



### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک



شماره صفحه: 8 از 58

| ىيمان: | شماده |
|--------|-------|
| ييسان. | سسرت  |

 $\cdot \Delta \mathbf{r} - \cdot \mathbf{V} \mathbf{r} - \mathbf{q} \, \mathbf{1} \mathbf{A} \mathbf{r}$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |  |  |

### 8.0 ATTACHMENTS

### 8.1 APPENDIX A -TEAM MEMBERS

| First Name    | Last Name          | Company         | Expertise                                |
|---------------|--------------------|-----------------|--|
| S.Mehdi       | Ashrafian          | NISOC           | Project Manager                          |
| Shamsolah     | Bahadori           | NISOC           | Construction Manager                     |
| Fatemeh       | Ghodsi             | NISOC           | Head of I&C                              |
| Mohammad      | Torfi              | NISOC           | Process                                  |
| Sahar         | Saba               | NISOC           | Process                                  |
| Niloofar      | Rezaei Baba ahmadi | NISOC           | Process                                  |
| Mohammad Reza | Cheraghchi         | NISOC           | Process                                  |
| Fazel         | Moafi              | NISOC           | Instrument                               |
| Behzad        | Zandian            | NISOC           | Instrument                               |
| Peyman        | Sarvarian          | NISOC           | Mechanic                                 |
| Hojjat        | Jafarpour          | NISOC           | Mechanical                               |
| Faride        | Parvin             | NISOC           | Mechanical                               |
| Mohammad      | Khamisi            | NISOC           | HSE                                      |
| Mohammad      | Shirali            | NISOC           | Commissioning                            |
| Ali           | Hamidan            | NISOC           | Commissioning                            |
| Naji          | Hamid              | NISOC           | Commissioning                            |
| Khodadad      | Kavosi             | NISOC           | Commissioning                            |
| Reza          | Gholgheysari       | NISOC           | Process Engineer                         |
| Mobin         | Saeedi             | NISOC           | Instrument                               |
| Mohammad      | Bakhshi Mohammadi  | Gachsaran NISOC | Production Engineer                      |
| Shahram       | Valizadeh          | Gachsaran NISOC | Production Engineer                      |
| Vahid         | Mussavi            | Gachsaran NISOC | Production Engineer                      |
| Mohammad      | Fakoor             | PEDCO           | Process Engineer                         |
| Farshid       | Amiri              | PEDCO           | Piping Lead Engineer                     |
| Hadi          | Mozaffari          | PEDCO           | Electrical Engineer                      |
| Mahdi         | Karimi             | PEDCO           | Head of Electrical Department            |
| Pouria        | Bavarsad           | PEDCO           | Piping Engineering                       |
| Sadegh        | Gharacheh          | PEDCO           | Process                                  |
| Morteza       | Taherkhani         | PEDCO           | Head of I&C                              |
| Sepideh       | Akbari             | PEDCO           | I&C Engineer                             |
| Sasan         | Faramarzpour       | PEDCO           | Head of Process and Safety<br>Department |
| Pouya         | Maleki             | PEDCO           | Process Engineer                         |











# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |        |      |  |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|--------|------|--|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سر يال | نسخه |  |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004   | D00  |  |  |  |

شماره صفحه: 9 از 58

| First Name | Last Name   | Company          | Expertise                |
|------------|-------------|------------------|--------------------------|
| Mehdi      | Sadeghian   | PEDCO            | Surface Manager          |
| Vahid      | Abdeshadi   | PEDCO            | Project Engineer Manager |
| Masoud     | Asgharnejad | Hirgan Energy    | Engineering Manager      |
| Mohsen     | Aryafar     | Hirgan Energy    | Process                  |
| Saeed      | Ghanbari    | Hirgan Energy    | Process                  |
| Parisa     | Hajisadeghi | Hirgan Energy    | Head of I&C              |
| Mohammad   | Fakharian   | Hirgan Energy    | Project Manager          |
| Ali        | Baghaei     | HAZOP Consultant | Process Safety           |
| Firoozeh   | Khosravi    | HAZOP Consultant | Process Safety           |



# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک











 $\cdot \Delta \mathbf{r} - \cdot \mathbf{V} \mathbf{r} - \mathbf{q} \, \mathbf{1} \mathbf{A} \mathbf{r}$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |  |  |
|                                     |           |            |         |      |          |       |      |  |  |  |

شماره صفحه: 10 از 58

#### 8.2 **APPENDIX B - DRAWINGS LIST**

| Drawing No.                     | Drawing Title                                      | Place(s) Used |
|---------------------------------|--|---------------|
| BK-GCS-PEDCO-120-PR-PI-0002_D03 | Gas Compression Inlet Gas Pipeline (Binak)         | Nodes: 1      |
| BK-GCS-PEDCO-120-PR-PI-0003_D03 | Gas Compression Inlet Gas Pipeline (Golkhari)      | Nodes: 2      |
| BK-GCS-PEDCO-120-PR-PI-0004_D03 | Slug Catcher System (2 sheets)                     | Nodes: 3      |
| BK-GCS-PEDCO-120-PR-PI-0005_D03 | Gas Compression Inlet Knock Out Drum               | Nodes: 4      |
| BK-GCS-PEDCO-120-PR-PI-0006_D03 | 1st Stage Gas Compression Suction Drums (3 sheets) | Nodes: 5      |
| BK-GCS-PEDCO-120-PR-PI-0007_D03 | 1st Stage Gas Compression Compressors (3 sheets)   | Nodes: 5      |
| BK-GCS-PEDCO-120-PR-PI-0008_D03 | 1st Stage Gas Compression Air Coolers (3 sheets)   | Nodes: 5      |
| BK-GCS-PEDCO-120-PR-PI-0009_D03 | 2nd Stage Gas Compression Suction Drums (3 sheets) | Nodes: 6      |
| BK-GCS-PEDCO-120-PR-PI-0010_D03 | 2nd Stage Gas Compression Compressors (3 sheets)   | Nodes: 6      |
| BK-GCS-PEDCO-120-PR-PI-0011_D03 | 2nd Stage Gas Compression Air Coolers (3 sheets)   | Nodes: 6      |
| BK-GCS-PEDCO-120-PR-PI-0012_D03 | 2nd Stage Gas Compression Discharge Drum           | Nodes: 7      |
| BK-GCS-PEDCO-120-PR-PI-0013_D03 | Gas Compression Dehydration Package (3 sheets)     | Nodes: 8      |
| BK-GCS-PEDCO-120-PR-PI-0014_D03 | Lean Glycol Storage Tank                           | Nodes: 9      |
| BK-GCS-PEDCO-120-PR-PI-0015_D03 | Instrument & Plant Air System                      | Nodes: 10     |
| BK-GCS-PEDCO-120-PR-PI-0016_D03 | Nitrogen Generation System                         | Nodes: 11     |
| BK-GCS-PEDCO-120-PR-PI-0017_D03 | Closed Drain System (2 sheets)                     | Nodes: 12     |
| BK-GCS-PEDCO-120-PR-PI-0018_D03 | Corrosion Inhibitor Package                        | Nodes: 13     |
| BK-GCS-PEDCO-120-PR-PI-0019_D03 | Methanol Injecktion Package                        | Nodes: 14     |
| BK-GCS-PEDCO-120-PR-PI-0020_D03 | LP Flare System (3 sheets)                         | Nodes: 15     |
| BK-GCS-PEDCO-120-PR-PI-0021_D03 | Oily Water Sewer                                   | Nodes: 16     |
| BK-GCS-PEDCO-120-PR-PI-0022_D03 | Fuel Gas System                                    | Nodes: 17     |
| BK-GCS-PEDCO-120-PR-PI-0023_D03 | Diesel Oil System (2 sheets)                       | Nodes: 18     |
| BK-GCS-PEDCO-120-PR-PI-0024_D03 | Potable Water System                               | Nodes: 19     |
| BK-GCS-PEDCO-120-PR-PI-0025_D03 | Glycol Sump Drum                                   | Nodes: 20     |







شماره صفحه: 11 از 58



# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

.24 - .74 - 9184

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|--|--|
| پروژه                               | بسته کاری | صادر كننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |  |  |

8.3 APPENDIX C - NODES LIST

| Nodes  | Color  | Туре         | Drawings                            | Equipment ID      | Date          |  |
|--|--------|--------------|-------------------------------------|-------------------|---------------|--|
| Gas Compression Inlet Gas     Pipeline (Binak)             | Red    | Pig Receiver | BK-GCS-PEDCO-120-PR-PI-<br>0002_D03 | PR-1002           | 2. 06/26/2022 |  |
| Gas Compression Inlet Gas     Pipeline (Golkhari)          | Violet | Pig Receiver | BK-GCS-PEDCO-120-PR-PI-<br>0003_D03 | PR-2102           | 2. 06/26/2022 |  |
| 3. Slug Catcher System                                     | L Blue | Drum         | BK-GCS-PEDCO-120-PR-PI-             | V-2104            | 2. 06/26/2022 |  |
|  |        | Pump         | 0004_D03                            | P-2101A/B         |               |  |
| Gas Compression Inlet     Knock Out Drum                   | Yellow | Drum         | BK-GCS-PEDCO-120-PR-PI-<br>0005_D03 | V-2105            | 3. 06/27/2022 |  |
| 5. 1st Stage Gas Compression<br>Suction Drums, Compressors | Blue   | Drum         | BK-GCS-PEDCO-120-PR-PI-<br>0006_D03 | V-2101A/B/C       | 3. 06/27/2022 |  |
| and Air Coolers  |        |              | BK-GCS-PEDCO-120-PR-PI-<br>0007_D03 | C-2101A/B/C       |               |  |
|  |        |              | BK-GCS-PEDCO-120-PR-PI-<br>0008_D03 | AE-2101A/B/C      |               |  |
| 6. 2nd Stage Gas Compression Suction Drums, Compressors    | Green  | Drum         | BK-GCS-PEDCO-120-PR-PI-<br>0009_D03 | V-2102A/B/C       | 3. 06/27/2022 |  |
| and Air Coolers  |        |              | BK-GCS-PEDCO-120-PR-PI-<br>0010_D03 | C-2102A/B/C       |               |  |
|  |        |              | BK-GCS-PEDCO-120-PR-PI-<br>0011_D03 | AE-2102A/B/C      |               |  |
| 7. 2nd Stage Gas Compression Discharge Drum                | Violet | Drum         | BK-GCS-PEDCO-120-PR-PI-<br>0012_D03 | V-2103            | 4. 06/28/2022 |  |
| Gas Compression     Dehydration Package                    | Yellow | Package      | BK-GCS-PEDCO-120-PR-PI-<br>0013_D03 | PK-2101           | 4. 06/28/2022 |  |
| 9. Lean Glycol Storage Tank                                | Blue   | Tank         | BK-GCS-PEDCO-120-PR-PI-             | TK-2102           | 4. 06/28/2022 |  |
|  |        | Pump         | 0014_D03                            | P-2102            | ]             |  |
|  |        |              |                                     | P-2103A/B         |               |  |
| 10. Instrument & Plant Air<br>System                       | Red    | Package      | BK-GCS-PEDCO-120-PR-PI-<br>0015_D03 | PK-DR-<br>2203A/B | 4. 06/28/2022 |  |
|  |        |              |                                     | PK-C-2203A/B      | =             |  |
|  |        |              |                                     | V-2203            |               |  |
| 11. Nitrogen Generation                                    | Green  | Package      | BK-GCS-PEDCO-120-PR-PI-             | PK-C-2204         | 4. 06/28/2022 |  |
| System   |        |              | 0016_D03                            | PK-G-2204         |               |  |
|  |        |              |                                     | V-2204            |               |  |
| 12. Closed Drain System                                    | Pink   | Drum         | BK-GCS-PEDCO-120-PR-PI-             | V-2202            | 4. 06/28/2022 |  |
|  |        | Pump         | 0017_D03                            | SU-2201           |               |  |
|  |        |              |                                     | P-2202A/B         |               |  |
|  |        |              |                                     | P-2203A/B         |               |  |
| 13. Corrosion Inhibitor Package                            | Orange | Line         | BK-GCS-PEDCO-120-PR-PI-             | PK-TK-2207        | 4. 06/28/2022 |  |



 $\cdot \Delta \mathbf{r} - \cdot \mathbf{V} \mathbf{r} - \mathbf{q} \, \mathbf{1} \mathbf{A} \mathbf{r}$ 

### نگهداشت و افزایش تولید میدان نفتی بینک سطح الارض







# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |  |  |

شماره صفحه: 12 از 58

| Nodes                          | Color  | Туре    | Drawings                            | Equipment ID       | Date          |  |
|--------------------------------|--------|---------|-------------------------------------|--------------------|---------------|--|
|                                |        | Package | 0018_D03                            | PK-<br>2207A/B/C/D |               |  |
|                                |        | Tank    |                                     | P-2207E            |               |  |
|                                |        | Pump    |                                     |                    |               |  |
| 14. Methanol Injection Package | L Blue | Line    | BK-GCS-PEDCO-120-PR-PI-<br>0019_D03 | -                  | 4. 06/28/2022 |  |
| 15. LP Flare System            | Violet | Line    | BK-GCS-PEDCO-120-PR-PI-             | -                  | 5. 06/29/2022 |  |
|                                |        |         |                                     | SU-2201            |               |  |
|                                |        | Package |                                     | V-2201             |               |  |
|                                |        |         |                                     | P-2201A/B          |               |  |
|                                |        |         |                                     | IG-2201            |               |  |
|                                |        |         |                                     | FST-2201           | =             |  |
| 16. Oily Water Sewer           | Yellow | Sump    | BK-GCS-PEDCO-120-PR-PI-<br>0021_D03 | SU-2202            | 5. 06/29/2022 |  |
| 17. Fuel Gas System            | Blue   | Drum    | BK-GCS-PEDCO-120-PR-PI-<br>0022_D03 | V-2205             | 5. 06/29/2022 |  |
| 18. Diesel Oil System          | Green  | Drum    | BK-GCS-PEDCO-120-PR-PI-             | V-2206A/B          | 5. 06/29/2022 |  |
|                                |        | Pump    | 0023D03                             | P-2206A/B          | =             |  |
| 19. Potable Water System       | L Blue | Tank    | BK-GCS-PEDCO-120-PR-PI-             | TK-2209            | 5. 06/29/2022 |  |
|                                |        | Pump    | 0024_D03                            | P-2209             | 1             |  |
| 20. Glycol Sump Drum           | Violet | Drum    | BK-GCS-PEDCO-120-PR-PI-             | V-2107             | 5. 06/29/2022 |  |
|                                |        | Pump    | 0025D03                             | P-2104             |               |  |



# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک









شماره پیمان:

 $\cdot \Delta \mathbf{r} - \cdot \mathbf{V} \mathbf{r} - \mathbf{q} \, \mathbf{1} \mathbf{A} \mathbf{r}$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |  |

شماره صفحه: 13 از 58

### 8.4 APPENDIX D - RECOMMENDATIONS LIST

|     | Recommendations  | Place(s) U            | sed      | Responsibility   | Status |
|-----|--|-----------------------|----------|------------------|--------|
|     | Define in operating procedure that operator should change capacity of compressors according to inlet flow of gas from Binak and Golkhari clusters. | Consequences: 2.1.1.1 | 1.1.1.1, | Contractor       | Closed |
| 2.  | Define low alarm on PI-2102.   | Consequences:         | 1.1.1.1  | Contractor       | Closed |
|     | General recommendation: Proxy limit switch signal of ESDVs in BINAK compressor station should be routed directly to DCS.                           | Consequences:         | 1.1.2.1  | Contractor       | Closed |
|     | Note on P&ID (BK-GCS-PEDCO-120-PR-PI-0002) Min distance for purge connection of Binak line to barred tee.  | Consequences:         | 1.6.1.1  | Contractor       | Closed |
|     | Relocate check valve and corrosion inhibitor injection of Binak gas to V-2105 to upstream of FCV-2101.   | Consequences:         | 1.6.1.1  | Contractor       | Closed |
| 6.  | Define low alarm on PI-2104.   | Consequences:         | 2.1.1.1  | Contractor       | Closed |
| 1   | Increase design pressure of piping from Golkhari pipeline tie-in point to FCV-2102 for protection against over pressure due to blocked outlet.     | Consequences: 2.4.1.1 | 2.1.2.2, | NISOC/Contractor | Closed |
| 8.  | Show on P&ID (BK-GCS-PEDCO-120-PR-PI-0003) purge connection of Golkhari line at min distance to barred tee.  | Consequences:         | 2.6.1.1  | Contractor       | Closed |
|     | Ball valve on tie-in point of 10" gas pipeline Golkhari BL should be full bore.  | Consequences:         | 2.8.1.1  | Contractor       | Closed |
| 10. | Consider future connection from Golkhari pipeline to existing gas compressor station downstream of MOV-2102B.                                      | Consequences:         | 2.8.1.1  | Contractor       | Closed |
| 11. | Remove auto start signal from LIC-2111 on P-2101A/B.   | Consequences:         | 3.1.1.1  | Contractor       | Closed |
| 12. | Define in operating manual of compressor station that on high level of V-2104 operator shall start P-2101A/B and open ESDV-2112.                   | Consequences:         | 3.1.1.1  | Contractor       | Closed |
| 13. | Define logic that PALL-2115 should be suppressed during pump P-2101A/B start.  | Consequences:         | 3.1.1.1  | Contractor       | Closed |
| 14. | Inlet isolation of V-2104 should be locked open.   | Consequences:         | 3.1.5.1  | Contractor       | Closed |
| 15. | Define in operating manual of compressor station that always one of bypass valve and inlet valve of V-2104 shall be open.                          | Consequences:         | 3.1.5.1  | Contractor       | Closed |
| 16. | Show on P&ID (BK-GCS-PEDCO-120-PR-PI-0004) pump pit for P-2101A/B.   | Consequences:         | 3.1.6.1  | Contractor       | Closed |
| 17. | Install check valve on 2" line from close drain pump P-2202A/B to V-2104.  | Consequences:         | 3.3.1.1  | Contractor       | Closed |
| 18. | Install TRV on pipeline from P-2101A/B to Binak cluster downstream of isolation valve of CGS BL.   | Consequences:         | 3.4.3.1  | Contractor       | Closed |
| 19. | Full vacuum should be considered for design pressure of V-2104.  | Consequences:         | 3.5.1.1  | Contractor       | Closed |
| 20. | 3" drain valves on V-2104 should be connected to close drain.  | Consequences:         | 3.8.1.1  | Contractor       | Closed |









# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\cdot \Delta \mathbf{r} - \cdot \mathbf{V} \mathbf{r} - \mathbf{q} \, \mathbf{1} \mathbf{A} \mathbf{r}$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |        |      |  |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|--------|------|--|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سر يال | نسخه |  |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004   | D00  |  |  |  |

شماره صفحه: 14 از 58

|     | Recommendations  | Place(s) Used                  | Responsibility | Status |
|-----|--|--------------------------------|----------------|--------|
| 21. | Suction and discharge flanges of P-2101A/B should be 300#.   | Consequences: 3.10.1.1         | Contractor     | Closed |
| 22. | Bypass valve of V-2104 should be ball type.  | Consequences: 3.10.1.1         | Contractor     | Closed |
| 23. | Show on P&ID (BK-GCS-PEDCO-120-PR-PI-0004) vent connection of P-2101.  | Consequences: 3.10.1.1         | Contractor     | Closed |
| 24. | Inlet isolation valve of V-2105 should be locked open.   | Consequences: 4.4.1.1          | Contractor     | Closed |
| 25. | Full vacuum should be considered for design pressure of V-2105.  | Consequences: 4.5.1.1          | Contractor     | Closed |
| 26. | Remove bypass over XV-2110.  | Consequences: 4.5.2.2          | Contractor     | Closed |
| 27. | LAHH-2117 should activate ESD-1.   | Consequences: 4.6.1.1          | Contractor     | Closed |
| 28. | LCV-2114 should be FC.   | Consequences: 4.7.1.1          | Contractor     | Closed |
| 29. | Valve arrangement on close drain connection of 1st stage gas compression manifold should be as ball valve, spectacle, check valve.   | Consequences: 4.8.1.1          | Contractor     | Closed |
| 30. | Consider spectacle blind on 2" drain line of V-2105, nozzle D.   | Consequences: 4.8.1.1          | Contractor     | Closed |
| 31. | Change type of 10" bypass valve over V-2105 to ball type.  | Consequences: 4.10.1.1         | Contractor     | Closed |
| 32. | Remove TIT-2111 and TIT-2113.  | Consequences: 4.10.1.1         | Contractor     | Closed |
| 33. | Remove LG-2115 and LIT-2116 from V-2105 and connect upper leg of LG-2116 and LIT-2119 to nozzle L1 of vessel.  | Consequences: 4.10.1.1         | Contractor     | Closed |
| 34. | Define in operating manual of compressor station that operator should adjust compressor capacity according to station flow rate.   | Consequences: 5.1.1.1          | Contractor     | Closed |
| 35. | Install check valve at 2nd stage discharge, downstream of spill back branch (at min distance to XV-2133A) and install check valve at inlet to each compressor train upstream of spill back branch. | Consequences: 5.2.1.1          | Contractor     | Closed |
| 36. | Consider limit switch for spill back valve PCV-2123A.  | Consequences: 5.2.1.1          | Contractor     | Closed |
| 37. | Study requirement to consider over pressure protection for V-2101 due to opening of spill back valve PCV-2123A.  | Consequences: 5.2.1.1          | Contractor     | Open   |
| 38. | Correct P&ID of air coolers of compressors according to data sheet.  | Consequences: 5.4.3.1, 6.4.3.1 | Contractor     | Closed |
| 39. | Consider block valves for N2 supply lines to compressor packages.  | Consequences: 5.10.1.1         | Contractor     | Closed |
| 40. | Consider maintenance lock for fan of air coolers in data sheet.  | Consequences: 5.10.1.1         | Contractor     | Closed |
| 41. | Consider drain connection on low point of line between V-2101A and compressor.   | Consequences: 5.11.1.1         | Contractor     | Closed |
| 42. | General recommendation: All solenoids with signal in ESD system should have manual reset.  | Consequences: 5.12.1.1         | Contractor     | Closed |
| 43. | Relocate sample connections of compressor suctions to Binak and Golkhari inlet lines and also on Inlet KO Drum outlet line.  | Consequences: 5.12.1.1         | Contractor     | Closed |









# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\cdot \Delta \mathbf{r} - \cdot \mathbf{V} \mathbf{r} - \mathbf{q} \, \mathbf{1} \mathbf{A} \mathbf{r}$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |  |  |

شماره صفحه: 15 از 58

|     | Recommendations  | Place(s) Used                 | Responsibility   | Status |
|-----|--|-------------------------------|------------------|--------|
| 44. | Provide XV with remote access for depressurizing of 1st stage suction drum of compressors to give more operability during maintenance. | Consequences: 6.7.2.2         | NISOC/Contractor | Closed |
| 45. | Define high level alarm on LT-2132 also define discrepancy alarm between LT-2131 and LT-2132 in DCS.                                   | SIL determination:<br>6.8.1.1 | Contractor       | Closed |
| 46. | Consider drain connection on low point of line between V-2102A and compressor.   | Consequences: 6.11.1.1        | Contractor       | Closed |
| 47. | Remove sample connection on suction and discharge of compressor 2nd stage.   | Consequences: 6.12.1.1        | Contractor       | Closed |
| 48. | Correct on P&ID that outlet pipe of BDV 2141 is connected directly to flare header separated from tail pipe of PSVs                    | Consequences: 7.5.1.1         | Contractor       | Closed |
| 49. | Full vacuum should be considered for design pressure of V-2103.  | Consequences: 7.5.2.1         | Contractor       | Closed |
| 50. | Show on P&ID stand pipe for LG-2141 and LIT-2141.  | Consequences: 7.6.1.1         | Contractor       | Closed |
| 51. | As per drain configuration, consider gate valve, spectacle and globe valve arrangement for bypass of XV-2144.                          | Consequences: 7.7.1.2         | Contractor       | Closed |
| 52. | Consider spectacle blind on B2 nozzle of V-2103.   | Consequences: 7.8.1.1         | Contractor       | Closed |
| 53. | Consider spectacle blind on corrosion inhibitor injection line to V-2103 after check valve.  | Consequences: 7.8.1.1         | Contractor       | Closed |
| 54. | Show on P&ID line number and inlet reducer of XV-2143.   | Consequences: 7.10.1.1        | Contractor       | Closed |
| 55. | Remove TG-2143.  | Consequences: 7.10.1.1        | Contractor       | Closed |
| 56. | Define high alarm on PIC-2152.   | Consequences: 8.1.1.1         | Contractor       | Closed |
| 57. | Show dedicated control blocks for PCV-2152 and PCV-2151.   | Consequences: 8.1.1.1         | Contractor       | Closed |
| 58. | Failure mode of PCV-2151 should be FC and failure mode of PCV-2152 should be FO.   | Consequences: 8.1.2.2         | Contractor       | Closed |
| 59. | Class of PCV-2151, PCV-2152 and BDV-2151 should be 600#.   | Consequences: 8.1.2.2         | Contractor       | Closed |
| 60. | General recommendation: check size of control valves to be compatible with IPS requirements.   | Consequences: 8.1.2.2         | Contractor       | Closed |
| 61. | Consider check valve on 2" closed drain connection from dehydration package.   | Consequences: 8.3.1.1         | Contractor       | Closed |
| 62. | Check with vendor requirement for sizing PSV on dehydration package for blocked outlet scenario.                                       | Consequences: 8.4.1.1         | Contractor       | Open   |
| 63. | Define low alarm on PIC-2152.  | Consequences: 8.5.1.1         | Contractor       | Closed |
| 64. | Show on P&ID of dehydration package detail of corrosion inhibitor injection valving.   | Consequences: 8.6.1.1         | Contractor       | Closed |
| 65. | Equalizing valve on bypass of dehydration package should be 2" and gate valve on this bypass should be changed to ball valve.          | Consequences: 8.7.1.1         | Contractor       | Closed |
| 66. | Consider block valve of fuel gas supply line to dehydration package.   | Consequences: 8.7.1.1         | Contractor       | Closed |









# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\cdot \Delta \mathbf{r} - \cdot \mathbf{V} \mathbf{r} - \mathbf{q} \, \mathbf{1} \mathbf{A} \mathbf{r}$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |  |  |

شماره صفحه: 16 از 58

|     | Recommendations  | Place(s) Used                      | Responsibility | Status |
|-----|--|------------------------------------|----------------|--------|
| 67. | Show on P&ID of dehydration package, BMS and min required signals to/from plant DCS and ESD.                                     | Consequences: 8.7.1.1              | Contractor     | Closed |
| 68. | HAZOP study of dehydration package shall be performed with participation of package vendor.                                      | Consequences: 8.7.1.1              | Contractor     | Closed |
| 69. | Correct on P&ID min flow (including RO) of P-2103A/B to be connected directly to nozzle B2 of TK-2102.                           | Consequences: 9.1.1.1              | Contractor     | Closed |
| 70. | Remove auto/manual signal from P-2103A/B.  | Consequences: 9.1.1.1              | Contractor     | Closed |
| 71. | Consider check valve on glycol line from P-2103A/B to PK-2101.   | Consequences: 9.3.1.1              | Contractor     | Closed |
| 72. | Blanketing of TK-2102 should be with N2.   | Consequences: 9.4.1.1              | Contractor     | Closed |
| 73. | Consider safety hatch for TK-2102.   | Consequences: 9.4.1.1              | Contractor     | Closed |
| 74. | Consider pressure transmitter with high and low alarm on TK-2102.  | Consequences: 9.4.1.1              | Contractor     | Closed |
| 75. | PVSV-2161/2162 should be vented to ATM.  | Consequences: 9.4.1.1              | Contractor     | Closed |
| 76. | Show vacuum set point of PVSV-2161/2162.   | Consequences: 9.5.1.1              | Contractor     | Closed |
| 77. | LIT-2161 and LIT-2162 should be readable at grade in loading area.   | Consequences: 9.6.1.1              | Contractor     | Closed |
| 78. | Consider spectacle blind on 2" drain nozzle D of TK-2102.  | Consequences: 9.8.1.1              | Contractor     | Closed |
| 79. | Remove check valve on suction of P-2103A/B.  | Consequences: 9.10.1.1             | Contractor     | Closed |
| 80. | Correct P&ID of glycol tank and show nozzle A at top of tank.  | Consequences: 9.10.1.1             | Contractor     | Closed |
| 81. | Consider PG on discharge of P-2102.  | Consequences: 9.10.1.1             | Contractor     | Closed |
| 82. | Number, signal and set points of PTs (PT-2203) for start/stop of standby air compressor should be according to IPS requirements. | Consequences: 10.1.1.1             | Contractor     | Closed |
| 83. | ESD level on PALL-2201A/B/C should be 1A.  | Consequences: 10.1.1.1<br>10.1.4.1 | Contractor     | Closed |
| 84. | PCV-2201 should be FC.   | Consequences: 10.1.2.1             | Contractor     | Closed |
| 85. | Remove ESDV-2231 and consider solenoid on PCV-2201 to close valve by ESD-3.  | Consequences: 10.1.3.1             | Contractor     | Closed |
| 86. | Remove mechanical trap from V-2203 and consider mechanical trap for wet air KO drum.   | Consequences: 10.7.1.1             | Contractor     | Closed |
| 87. | PCV-2211 should be FO.   | Consequences: 11.1.2.1             | Contractor     | Closed |
| 88. | Consider check valve on nitrogen branches to gas compressors.  | Consequences: 11.3.1.1             | Contractor     | Closed |
| 89. | Remove mechanical trap from V-2204 and consider mechanical trap for wet air KO drum inside compressor package.                   | Consequences: 11.7.1.1             | Contractor     | Closed |
| 90. | Remove HC analyzer from nitrogen package.  | Consequences: 11.8.1.1             | Contractor     | Closed |
| 91. | Consider check valve on 2" line from P-2201A/B to existing burn pit.   | Consequences: 12.1.1.1             | Contractor     | Closed |
| 92. | Remove 2" line connection from closed drain drum to oily   | Consequences: 12.1.1.1             | Contractor     | Closed |









# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\bullet \Delta \Upsilon - \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |  |

شماره صفحه: 17 از 58

|     | Recommendations  | Place(s) Used                    | Responsibility | Status |
|-----|--|----------------------------------|----------------|--------|
|     | water sump.  |                                  |                |        |
| 93. | Globe valve on flare nozzle of V-2202 should be changed to ball type.  | Consequences: 12.2.1.1           | Contractor     | Closed |
| 94. | Full vacuum should be considered for design pressure of V-2202.  | Consequences: 12.3.1.1           | Contractor     | Closed |
| 95. | LIT-2223A/B should be float type and consider only one common LT for P-2203A/B.                                | Consequences: 12.4.2.1           | Contractor     | Closed |
| 96. | Relocate PALL-2222A/B to between pumps P-2202A/B and suction strainers.  | Consequences: 12.5.1.1           | Contractor     | Closed |
| 97. | Consider spectacle blind on inlet and outlet of P-2201A/B.   | Consequences: 12.6.1.1           | Contractor     | Closed |
| 98. | Relocate PIT-2252 (currently PIT-2222A) from closed drain drum to flare KO drum.                               | Consequences: 12.7.1.1           | Contractor     | Closed |
| 99. | valves down stream of P-2202A/B to V-2104 should be LO.  | Consequences: 12.7.1.1           | Contractor     | Closed |
| 100 | . Consider PG at discharge of P-2202A/B.   | Consequences: 12.7.1.1           | Contractor     | Closed |
| 101 | . Consider remote stop for corrosion inhibitor package (XSP corrected to HSP).                                 | Consequences: 13.1.1.1           | Contractor     | Closed |
| 102 | . Check coverage of CCTV and if required consider CCTV for flare monitoring in control room.                   | Consequences: 15.1.1.1           | Contractor     | Closed |
| 103 | . Relocate PALL-2251A/B to between pumps P-2201A/B and suction strainers.                                      | Consequences: 15.7.1.1           | Contractor     | Closed |
| 104 | . Consider spectacle blinds on suction and discharge isolation valves of P-2201A/B.                            | Consequences: 15.8.1.1           | Contractor     | Closed |
| 105 | . Define in operating manual that operator should ensure that always one discharge route of P-2201A/B is open. | Consequences: 15.8.1.1           | Contractor     | Closed |
| 106 | . LIT-2273 should be float type with cage.   | Consequences: 16.1.1.1           | Contractor     | Closed |
| 107 | . Define low alarm on PI-2271.   | Consequences: 17.1.2.1, 17.1.4.1 | Contractor     | Closed |
| 108 | . Replace PRV-2272 with local flow gauge, ball valve, check valve and globe valve.                             | Consequences: 17.1.3.1           | Contractor     | Closed |
| 109 | . PSV on V-2205 should be sized for fire case.   | Consequences: 17.4.1.1           | Contractor     | Closed |
| 110 | . Full vacuum should be considered for design pressure of V-2205.  | Consequences: 17.5.1.1           | Contractor     | Closed |
| 111 | . Note in duty spec of dehydration package that requirement for fuel gas filter should be checked by vendor.   | Consequences: 17.9.1.1           | Contractor     | Closed |
| 112 | . Remove fuel gas lines used for blanketing of TK-2102 and V-2107.   | Consequences: 17.10.1.1          | Contractor     | Closed |
| 113 | . Remove PT-2281A/B from suction of P-2206A/B and consider local pressure gauge.                               | Consequences: 18.1.3.1           | Contractor     | Closed |
| 114 | . Define high high and low low trip interlock on LI-2281A/B to trip P-2206A/B.                                 | Consequences: 18.1.3.1           | Contractor     | Closed |
| 115 | . Any surface contamination on diesel oil drum area  | Consequences: 18.6.1.1           | Contractor     | Closed |











# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\cdot \Delta \mathtt{T} - \cdot \mathtt{VT} - \mathtt{91} \mathtt{AF}$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |  |

شماره صفحه: 18 از 58

|      | Recommendations  | Place(s) Used                    | Responsibility | Status |
|------|--|----------------------------------|----------------|--------|
|      | should be directed to oily water header.   |                                  |                |        |
| 116. | Remove steam out connection for V-2206A/B.   | Consequences: 18.8.1.1           | Contractor     | Closed |
| 117. | Relocate globe valve at discharge of P-2206A/B to downstream of tank filling branch.         | Consequences: 18.8.1.1           | Contractor     | Closed |
| 118. | Consider drain connection at suction and discharge of P-2206A/B.                             | Consequences: 18.8.1.1           | Contractor     | Closed |
| 119. | Remove ESD-1 signal from P-2209.   | Consequences: 19.1.1.1           | Contractor     | Closed |
| 120. | Remove start signal from LT-2293 on P-2104.  | Consequences: 20.1.1.1           | Contractor     | Closed |
| 121. | Consider proper type for LIT-2293.   | Consequences: 20.1.1.1           | Contractor     | Open   |
| 122. | Consider PSV on V-2207 sized for regulator failure and fire case scenario.                   | Consequences: 20.3.1.1, 20.3.2.1 | Contractor     | Closed |
| 123. | Consider PT with high alarm on V-2107.   | Consequences: 20.3.3.1           | Contractor     | Closed |
| 124. | Full vacuum should be considered for design pressure of V-2107.                              | Consequences: 20.4.1.1           | Contractor     | Closed |
| 125. | Consider isolation valve downstream of PRV-2291.   | Consequences: 20.7.1.1           | Contractor     | Closed |
| 126. | Consider spectacle on inlet and outlet lines (nozzle A, nozzle B and pump outlet) of V-2107. | Consequences: 20.7.1.1           | Contractor     | Closed |
| 127. | Consider drain connection under V-2107.  | Consequences: 20.7.1.1           | Contractor     | Closed |
| 128. | Consider slop for V-2107 towards pump side.  | Consequences: 20.7.1.1           | Contractor     | Closed |
| 129. | Consider connection from P-2104 to oily water system.  | Consequences: 20.8.1.1           | Contractor     | Closed |
| 130. | ESD level on P-2104 should be ESD-1A.  | Consequences: 20.9.1.1           | Contractor     | Closed |
| 131. | Consider connection for loading spent glycol to truck downstream of P-2104.                  | Consequences: 20.9.1.1           | Contractor     | Closed |



# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک









شماره پیمان:

.04 - . 14 - 9114

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |

شماره صفحه: 19 از 58

### 8.5 APPENDIX E – HAZOP WORKSHEETS

Node: 1. Gas Compression Inlet Gas Pipeline (Binak)

Deviation: 1. No/Less Flow

| Causes  | Consequences  | Safeguards  | Recommendations  |
|---|---|---|--|
| No/less flow from upstream<br>due to any reason                             | Low suction pressure for station and waste of energy                              | Low suction pressure protection of compressor   | Define in operating procedure that operator should change capacity of compressors according to inlet flow of gas from Binak and Golkhari clusters. |
|   |   | Low pressure alarm<br>on compressor 1st<br>stage and spill back<br>control                | 2. Define low alarm on PI-2102.  |
|   |   | 3. FAL-2101   |  |
| ESDV-2101 closed by failure or error  | Low suction pressure for<br>station and decreased<br>production                   | Low suction pressure protection of compressor   | 3. General recommendation: Proxy limit switch signal of ESDVs in BINAK compressor  |
|   |   | Low pressure alarm<br>on compressor 1st<br>stage and spill back<br>control                | station should be routed directly to DCS.  |
|   |   | 3. Limit switch on valve  |  |
|   |   | 4. FAL-2101   |  |
|   | Increased pressure upstream<br>of valve with possibility of<br>damage to pipeline | High pressure protection in Binak Cluster   |  |
|   | High pressure at inlet of existing station  | High pressure     protection (flare) in     existing Binak gas     station inlet K.O drum |  |
| FCV-2101 closed more by a<br>failure in any elements of its<br>control loop | 1. Same as above  | Low suction pressure protection of compressor   |  |
|   |   | Low pressure alarm<br>on compressor 1st<br>stage and spill back<br>control                |  |
|   |   | 3. FAL-2101 (dependent)   |  |
|   |   | High pressure protection in Binak Cluster   |  |
|   |   | 5. High pressure protection (flare) in existing Binak gas station inlet K.O drum          |  |





# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک



شماره پیمان:  $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |        |      |
|-------------------------------------|-----------|------------|---------|------|----------|--------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سر يال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004   | D00  |

شماره صفحه: 20 از 58

Node: 1. Gas Compression Inlet Gas Pipeline (Binak)

Deviation: 2. More Flow

| Causes  | Consequences  | Safeguards   | Recommendations |
|---|---|--|-----------------|
| FCV-2101 open more by a failure in any elements of its control loop | hazardous consequence for                                   | See Dehydration     package node for     safeguard |                 |
|   | compressors but decreased efficiency of dehydration package | 2. FAH-2101<br>(dependent)                         |                 |

Node: 1. Gas Compression Inlet Gas Pipeline (Binak)

Deviation: 3. Reverse/Misdirected Flow

| Causes                                     | Consequences | Safeguards | Recommendations |
|--|--------------|------------|-----------------|
| Check valves are considered where required |              |            |                 |

Node: 1. Gas Compression Inlet Gas Pipeline (Binak)

Deviation: 4. High Pressure

| Causes   | Consequences                                    | Safeguards                         | Recommendations |
|--|---|------------------------------------|-----------------|
| High pressure from Binak cluster due to any reason | No hazardous consequence due to design pressure |                                    |                 |
| Shutdown of downstream compressor station          | Binak cluster max pressure                      | PAHH-2116 that will activate ESD-1 |                 |
|  | with possibility of damage to inlet K.O drum    | 2. PSV-2113/2114 on V-<br>2105     |                 |

Node: 1. Gas Compression Inlet Gas Pipeline (Binak)

Deviation: 5. Low Pressure

| Causes                         | Consequences | Safeguards | Recommendations |
|--------------------------------|--------------|------------|-----------------|
| 1. No new issue was identified |              |            |                 |

Node: 1. Gas Compression Inlet Gas Pipeline (Binak)

Deviation: 6. Maintenance Hazards

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 4. Note on P&ID (BK-GCS-<br>PEDCO-120-PR-PI-0002) Min<br>distance for purge connection<br>of Binak line to barred tee. |
|                       |              |            | 5. Relocate check valve and corrosion inhibitor injection of Binak gas to V-2105 to upstream of FCV-2101.              |









شماره صفحه: 21 از 58



# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان: ۹۱۸۴ – ۰۷۳ – ۰۵۳

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |        |      |
|-------------------------------------|-----------|------------|---------|------|----------|--------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سر يال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004   | D00  |

Node: 1. Gas Compression Inlet Gas Pipeline (Binak)

Deviation: 7. Corrosion

| Causes                              | Consequences                   | Safeguards                    | Recommendations |
|-------------------------------------|--------------------------------|-------------------------------|-----------------|
| Moisture and sulphur content in gas | Damage to equipment and piping | Corrosion monitoring (CP/CC)  |                 |
|                                     |                                | Corrosion inhibitor injection |                 |

Node: 2. Gas Compression Inlet Gas Pipeline (Golkhari)

Deviation: 1. No/Less Flow

| Causes                                       | Consequences   | Safeguards   | Recommendations  |
|--|--|--|--|
| No/less flow from upstream due to any reason | Low suction pressure for station and waste of energy   | Low suction pressure protection of compressor                              | Define in operating procedure that operator should change capacity of compressors according to inlet flow of gas from Binak and Golkhari clusters. |
|  |  | Low pressure alarm<br>on compressor 1st<br>stage and spill back<br>control | 6. Define low alarm on PI-2104.  |
|  |  | 3. FAL-2102  |  |
| 2. MOV-2102B closed by error                 | Low suction pressure for<br>station and decreased<br>production                                      | Low suction pressure protection of compressor                              |  |
|  |  | Low pressure alarm<br>on compressor 1st<br>stage and spill back<br>control |  |
|  |  | 3. Limit switch on valve   |  |
|  |  | 4. FAL-2102  |  |
|  | Increased pressure upstream<br>of valve with possibility of<br>damage to piping upstream<br>of valve |  | 7. Increase design pressure of piping from Golkhari pipeline tie-in point to FCV-2102 for protection against over pressure due to blocked outlet.  |
| ESDV-2102 closed by failure or error         | Low suction pressure for<br>station and decreased<br>production                                      | Low suction pressure protection of compressor                              |  |
|  |  | Low pressure alarm<br>on compressor 1st<br>stage and spill back<br>control |  |
|  |  | 3. Limit switch on valve   |  |
|  |  | 4. FAL-2102  |  |
|  | 2. Increased pressure upstream   |  |  |





# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

| شماره پیمان: |  |
|--------------|--|
| .0404 - 9184 |  |
| · W1 · V1    |  |

| HAZOP REPORT FOR COMPRESSOR STATION                        |     |       |     |    |    |      |      |
|--|-----|-------|-----|----|----|------|------|
| نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پروژه |     |       |     |    |    |      | نسخه |
| BK   | GCS | PEDCO | 120 | GE | RT | 0004 | D00  |

شماره صفحه: 22 از 58

Node: 2. Gas Compression Inlet Gas Pipeline (Golkhari)

Deviation: 1. No/Less Flow

| Causes  | Consequences  | Safeguards   | Recommendations |
|---|---|--|-----------------|
|   | of valve with possibility of damage to piping upstream of valve |  |                 |
| FCV-2102 closed more by a<br>failure in any elements of its<br>control loop |   | Low suction pressure protection of compressor                              |                 |
|   |   | Low pressure alarm<br>on compressor 1st<br>stage and spill back<br>control |                 |
|   |   | 3. FAL-2102 (dependent)  |                 |

Node: 2. Gas Compression Inlet Gas Pipeline (Golkhari)

Deviation: 2. More Flow

| Causes  | Consequences  | Safeguards   | Recommendations |
|---|---|--|-----------------|
| FCV-2102 open more by a failure in any elements of its control loop | Increased pressure in<br>compressor suction with no<br>hazardous consequence for<br>compressors but decreased<br>efficiency of dehydration<br>package | See Dehydration package node for safeguard      FAH-2102 (dependent) |                 |

Node: 2. Gas Compression Inlet Gas Pipeline (Golkhari)

Deviation: 3. Reverse/Misdirected Flow

| Causes                                     | Consequences | Safeguards | Recommendations |
|--|--------------|------------|-----------------|
| Check valves are considered where required |              |            |                 |

Node: 2. Gas Compression Inlet Gas Pipeline (Golkhari)

Deviation: 4. High Pressure

| Causes  | Consequences   | Safeguards                         | Recommendations   |
|---|--|------------------------------------|---|
| High pressure from Golkhari cluster due to any reason | Possibility of damage to piping due to over pressure and fire and personnel injury |                                    | 7. Increase design pressure of piping from Golkhari pipeline tie-in point to FCV-2102 for protection against over pressure due to blocked outlet. |
| Shutdown of downstream compressor station             | Increased pressure up to<br>Golkhari cluster max                                   | PAHH-2111 that will activate ESD-1 |   |
|   | pressure with possibility of damage to slug catcher                                | 2. PSV-2111/2112 on V-<br>2104     |   |









# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان: ۹۱۸۴ – ۰۷۳ – ۰۵۳

|   | HAZOP REPORT FOR COMPRESSOR STATION |  |  |  |  |  |  |  |
|---|-------------------------------------|--|--|--|--|--|--|--|
| نسخه سریال نوع مدرک رشته تسهیلات صادر کننده بسته کاری پروژه |                                     |  |  |  |  |  |  |  |
| BK GCS PEDCO 120 GE RT 0004 D00                             |                                     |  |  |  |  |  |  |  |

شماره صفحه: 23 از 58

Node: 2. Gas Compression Inlet Gas Pipeline (Golkhari)

Deviation: 5. Low Pressure

| Causes                         | Consequences | Safeguards | Recommendations |
|--------------------------------|--------------|------------|-----------------|
| 1. No new issue was identified |              |            |                 |

Node: 2. Gas Compression Inlet Gas Pipeline (Golkhari)

Deviation: 6. Maintenance Hazards

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 8. Show on P&ID (BK-GCS-PEDCO-120-PR-PI-0003) purge connection of Golkhari line at min distance to barred tee. |

Node: 2. Gas Compression Inlet Gas Pipeline (Golkhari)

Deviation: 7. Corrosion

| Causes                              | Consequences                   | Safeguards                    | Recommendations |
|-------------------------------------|--------------------------------|-------------------------------|-----------------|
| Moisture and sulphur content in gas | Damage to equipment and piping | Corrosion monitoring (CP/CC)  |                 |
|                                     |                                | Corrosion inhibitor injection |                 |

Node: 2. Gas Compression Inlet Gas Pipeline (Golkhari)

Deviation: 8. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | Ball valve on tie-in point of 10"<br>gas pipeline Golkhari BL should<br>be full bore.  |
|                       |              |            | <ol> <li>Consider future connection<br/>from Golkhari pipeline to<br/>existing gas compressor<br/>station downstream of MOV-<br/>2102B.</li> </ol> |

Node: 3. Slug Catcher System Deviation: 1. No/Less Flow

| Causes                                | Consequences   | Safeguards      | Recommendations  |
|---------------------------------------|--|-----------------|--|
| P-2101A/B fail to start when required | Accumulation of liquid in slug catcher with no hazardous | 1. LAH-2111     | 11. Remove auto start signal from LIC-2111 on P-2101A/B.   |
|                                       | consequence  | 2. Standby pump | 12. Define in operating manual of compressor station that on high level of V-2104 operator shall start P-2101A/B and |



 $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

### نگهداشت و افزایش تولید میدان نفتی بینک سطح الارض



### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

120

GE

HAZOP REPORT FOR COMPRESSOR STATION شماره صفحه: 24 از 58 صادر کننده نسخه تسهيلات رشته نوع مدرك سر يال

 $\mathsf{RT}$ 

D00

0004

Node: 3. Slug Catcher System Deviation: 1. No/Less Flow

شماره پیمان:

بسته کاری

GCS

PEDCO

پروژه

ΒK

| Causes  | Consequences   | Safeguards  | Recommendations   |
|---|--|---|---|
|   |  |   | open ESDV-2112.   |
|   |  |   | 13. Define logic that PALL-2115 should be suppressed during pump P-2101A/B start.           |
| 2. Plugging of pump strainer  | Possibility of damage to pump  | PALL-2114A/B that<br>will activate ESD-3<br>and stop pump P-<br>2101A/B |   |
|   |  | 2. Local PDG-2114A/B  |   |
| FCV-2111 closed more by a failure in any elements of its control loop | Possibility of damage to pump due to high pressure                                       | PAHH-2116A/B that will activate ESD-3                                   |   |
| ESDV-2112 closed by failure or error                                  | 1. Same as above   | 1. Limit switch on valve  |   |
| Downstream compressor shutdown  | High pressure of V-2104 up to Golkhari cluster pressure                                  | PAHH-2111 that will activate ESD-1                                      | 14. Inlet isolation of V-2104 should be locked open.  |
|   | with possibility of damage, fire and injury  | 2. PAH-2112   | 15. Define in operating manual of   |
|   | , ,  | 3. PSV-2111/2112 on V-<br>2104  | compressor station that always one of bypass valve and inlet valve of V-2104 shall be open. |
| Plugging of demister pad in<br>V-2104                                 | Low suction pressure for<br>compressors and also<br>possibility of damage to<br>demister | 1. PDAH-2111  | 16. Show on P&ID (BK-GCS-PEDCO-120-PR-PI-0004) pump pit for P-2101A/B.                      |

#### Node: 3. Slug Catcher System

Deviation: 2. More Flow

| Causes  | Consequences | Safeguards                     | Recommendations |
|---|--------------|--------------------------------|-----------------|
| FCV-2111 open more by a failure in any elements of its control loop |              | Over current protection in MCC |                 |

### Node: 3. Slug Catcher System

Deviation: 3. Reverse/Misdirected Flow

| Causes   | Consequences | Safeguards | Recommendations   |
|--|--------------|------------|---|
| 1. See Recommendation  |              |            | 17. Install check valve on 2" line from close drain pump P-2202A/B to V-2104. |
| Check valves are considered where required for other streams |              |            |   |







شماره صفحه: 25 از 58



# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\bullet \Delta \Psi - \bullet V \Psi - \P \, \mathsf{I} \, \mathsf{A} \, \mathsf{F}$ 

| HAZOP REPORT FOR COMPRESSOR STATION                         |  |  |  |  |  |  |
|---|--|--|--|--|--|--|
| نسخه سریال نوع مدرک رشته تسهیلات صادر کننده بسته کاری پروژه |  |  |  |  |  |  |
| BK GCS PEDCO 120 GE RT 0004 D00                             |  |  |  |  |  |  |

Node: 3. Slug Catcher System

Deviation: 4. High Pressure

| Causes   | Consequences        | Safeguards                     | Recommendations  |
|--|---------------------|--------------------------------|--|
| 1. External fire case for V-2104   | Damage to equipment | 1. PSV-2111/2112 on V-<br>2104 |  |
| Blocked outlet at gas line<br>from V-2104  | Damage to equipment | 1. PSV-2111/2112 on V-<br>2104 |  |
| Line box-in and thermal<br>expansion for pipeline from<br>P-2101A/B to Binak cluster | Damage to pipeline  |                                | 18. Install TRV on pipeline from P-2101A/B to Binak cluster downstream of isolation valve of CGS BL. |

Node: 3. Slug Catcher System Deviation: 5. Low Pressure

| Causes                                      | Consequences                             | Safeguards | Recommendations   |
|---|--|------------|---|
| Maloperation during steam<br>out at startup | Vacuum formation and V-<br>2104 collapse |            | 19. Full vacuum should be considered for design pressure of V-2104. |

Node: 3. Slug Catcher System Deviation: 6. High Level

| Causes  | Consequences                             | Safeguards   | Recommendations |
|---|--|--|-----------------|
| Entrance of large amount of liquid to V-2104 due to | KO drum and compressors                  | LAHH-2112 that will activate ESD-1                             |                 |
| upset in Golkhari cluster                           | with possibility of damage to compressor | LAHH-2117 that will activate ESD-3 on inlet KO drum            |                 |
|   |  | 3. LAHH-2122A/B/C that will activate ESD-2 and trip compressor |                 |


Node: 3. Slug Catcher System

Deviation: 7. Low Level

| Causes   | Consequences   | Safeguards  | Recommendations |
|--|----------------|---|-----------------|
| P-2101A/B remain in service<br>when not required | Damage to pump | LAL-2111 that will stop pump                            |                 |
|  |                | LALL-2112 that will activate ESD-3 and stop pumps       |                 |
|  |                | 3. PALL-2114A/B that will activate ESD-3 and stop pumps |                 |









شماره پیمان:  $\bullet \Delta \Psi - \bullet V \Psi - \P \, \mathsf{I} \, \mathsf{A} \, \mathsf{F}$ 

| HAZOP REPORT FOR COMPRESSOR STATION                        |     |       |     |    |    |      |     |
|--|-----|-------|-----|----|----|------|-----|
| نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پروژه |     |       |     |    |    |      |     |
| BK   | GCS | PEDCO | 120 | GE | RT | 0004 | D00 |

شماره صفحه: 26 از 58

Node: 3. Slug Catcher System Deviation: 8. Maintenance Hazards

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 20. 3" drain valves on V-2104 should be connected to close drain. |

Node: 3. Slug Catcher System

Deviation: 9. Corrosion

| Causes  | Consequences                                | Safeguards  | Recommendations |
|---|---|---|-----------------|
| Corrosion due to sulphur and moisture content | Damage to equipment and piping in long term | Corrosion monitoring (CP/CC)                                      |                 |
|   |   | 2. Liquid line from V-<br>2104 to P-2101A/B is<br>Stainless Steel |                 |

Node: 3. Slug Catcher System Deviation: 10. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 21. Suction and discharge flanges of P-2101A/B should be 300#.                   |
|                       |              |            | 22. Bypass valve of V-2104 should be ball type.                                  |
|                       |              |            | 23. Show on P&ID (BK-GCS-<br>PEDCO-120-PR-PI-0004)<br>vent connection of P-2101. |

#### Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 1. No/Less Flow

| Causes                                | Consequences   | Safeguards                         | Recommendations |
|---------------------------------------|--|------------------------------------|-----------------|
| 1. Compressors shutdown due           | ·  |                                    |                 |
| to any reason                         | possibility of damage, fire and personnel injury   | PAHH-2116 that will activate ESD-1 |                 |
|                                       |  | 3. PSV-2113/2114 on V-<br>2105     |                 |
| Plugging of demister pad in<br>V-2105 | Low suction pressure for<br>compressors and also<br>possibility of damage to<br>demister | 1. PDAH-2112                       |                 |





# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک



شماره صفحه: 27 از 58



شماره پیمان:

 $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

|   | HAZOP REPORT FOR COMPRESSOR STATION |  |  |  |  |  |      |
|---|-------------------------------------|--|--|--|--|--|------|
| نسخه سريال نوع مدرك رشته تسهيلات صادركننده بسته كارى پروژه                              |                                     |  |  |  |  |  | نسخه |
| BK         GCS         PEDCO         120         GE         RT         0004         D00 |                                     |  |  |  |  |  |      |
|   |                                     |  |  |  |  |  |      |

Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 2. More Flow

| Causes                  | Consequences | Safeguards | Recommendations |
|-------------------------|--------------|------------|-----------------|
| No issue was identified |              |            |                 |

#### Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 3. Reverse/Misdirected Flow

| Causes                                     | Consequences | Safeguards | Recommendations |
|--|--------------|------------|-----------------|
| Check valves are considered where required |              |            |                 |

#### Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 4. High Pressure

| Causes                           | Consequences        | Safeguards                     | Recommendations  |
|----------------------------------|---------------------|--------------------------------|--|
| 1. External fire case for V-2105 | Damage to equipment | 1. PSV-2113/2114 on V-<br>2105 | 24. Inlet isolation valve of V-2105 should be locked open. |

### Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 5. Low Pressure

| Causes                                      | Consequences                             | Safeguards                                    | Recommendations   |
|---|--|---|---|
| Maloperation during steam<br>out at startup | Vacuum formation and V-<br>2105 collapse |   | 25. Full vacuum should be considered for design pressure of V-2105. |
| 2. XV-2110 open by failure or               | Waste of gas to flare with               | 1. Limit switch on valve                      |   |
| error                                       | environmental effect                     | 2. PAL-2117                                   |   |
|   | Loss of suction pressure for compressors | Low suction pressure protection of compressor | 26. Remove bypass over XV-<br>2110.                                 |

### Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 6. High Level

| Causes                                 | Consequences  | Safeguards  | Recommendations                      |
|--|---|---|--------------------------------------|
| LCV-2114 remained closed for long time | Accumulation of liquid in inlet     KO drum and carry over to | 1. LAH-2119<br>(dependent)  | 27. LAHH-2117 should activate ESD-1. |
|  | compressors suction drums and fuel gas KO drum                | LAHH-2117 that will activate ESD-3  |                                      |
|  |   | High level alarm protection on compressor suction drum and fuel gas KO drum |                                      |





# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

| TIRGAN |  |
|--------|--|
| NERGY  |  |
|        |  |

شماره پیمان:  $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

|  | HAZOP REPORT FOR COMPRESSOR STATION |       |     |    |    |      |     |  |
|--|-------------------------------------|-------|-----|----|----|------|-----|--|
| نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پروژه |                                     |       |     |    |    |      |     |  |
| BK   | GCS                                 | PEDCO | 120 | GE | RT | 0004 | D00 |  |
|  |                                     |       |     |    |    |      |     |  |

شماره صفحه: 28 از 58

Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 6. High Level

| Causes  | Consequences     | Safeguards | Recommendations |
|---|------------------|------------|-----------------|
| ESDV-2113 remained     closed by failure or error for     long time | 1. Same as above |            |                 |

#### Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 7. Low Level

| Causes                    | Consequences                     | Safeguards   | Recommendations            |
|---------------------------|----------------------------------|--|----------------------------|
| 1. LCV-2114 remained open | 1. Low level in V-2105 and gas   | 1. LAL-2119 (dependent)                                | 28. LCV-2114 should be FC. |
| when not required         | blowby via closed drain to flare | LALL-2118 that will activate ESD-3 and close ESDV-2113 |                            |

#### Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 8. Maintenance Hazards

| Causes                | Consequences | Safeguards   | Recommendations  |
|-----------------------|--------------|--|--|
| 1. See Recommendation |              | 29. Valve arrangement on drain connection of 1st gas compression mani should be as ball valve spectacle, check valve |  |
|                       |              |  | 30. Consider spectacle blind on 2" drain line of V-2105, nozzle D. |

### Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 9. Corrosion

| Causes  | Consequences                                | Safeguards   | Recommendations |
|---|---|--|-----------------|
| Corrosion due to sulphur and moisture content | Damage to equipment and piping in long term | Corrosion monitoring (CP/CC)                                     |                 |
|   |   | Corrosion inhibitor injection is considered                      |                 |
|   |   | 3. Liquid line from V-<br>2105 to LCV-2104 is<br>Stainless Steel |                 |

### Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 10. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 31. Change type of 10" bypass valve over V-2105 to ball type. |











# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان: ۹۱۸۴ – ۰۷۳ – ۰۵۳

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |        |      |
|-------------------------------------|-----------|------------|---------|------|----------|--------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سر يال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004   | D00  |

شماره صفحه: 29 از 58

Node: 4. Gas Compression Inlet Knock Out Drum

Deviation: 10. Miscellaneous

| Causes | Consequences | Safeguards | Recommendations  |
|--------|--------------|------------|--|
|        |              |            | 32. Remove TIT-2111 and TIT-<br>2113.  |
|        |              |            | 33. Remove LG-2115 and LIT-<br>2116 from V-2105 and<br>connect upper leg of LG-2116<br>and LIT-2119 to nozzle L1 of<br>vessel. |

Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 1. No/Less Flow

| Causes                            | Consequences   | Safeguards   | Recommendations  |                          |                          |                          |                          |                          |  |                          |                                     |  |
|-----------------------------------|--|--|--|--------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--|--------------------------|-------------------------------------|--|
| Decreased flow from               | Low suction pressure with                                      | 1. PAL-2121A   | 34. Define in operating manual of  |                          |                          |                          |                          |                          |  |                          |                                     |  |
| upstream due to any reason        | possibility of damage to<br>compressors due to over<br>heating | 2. PALL-2122A that will activate ESD-2   | compressor station that<br>operator should adjust<br>compressor capacity |                          |                          |                          |                          |                          |  |                          |                                     |  |
|                                   |  | 3. PAL-2123A/PAL-<br>2124A/PAL-<br>2132A/FAL-<br>2121A/FAL-2131A<br>inside compressor<br>package | according to station flow rate.  |                          |                          |                          |                          |                          |  |                          |                                     |  |
|                                   |  | Spill back valve will open by PIC-2121A  |  |                          |                          |                          |                          |                          |  |                          |                                     |  |
|                                   |  | 5. Internal high temperature protection in compressor package                                    |  |                          |                          |                          |                          |                          |  |                          |                                     |  |
| 2. XV-2121A closed by failure     | 1. Loss of suction pressure for                                | 1. PAL-2121A   |  |                          |                          |                          |                          |                          |  |                          |                                     |  |
| or error (any failure out of UCP) | one compressor with possibility of damage to                   | possibility of damage to   | possibility of damage to   | possibility of damage to | possibility of damage to | possibility of damage to | possibility of damage to | possibility of damage to |  | possibility of damage to | PALL-2122A that will activate ESD-2 |  |
|                                   | heating  | 3. PAL-2123A/PAL-<br>2124A/PAL-<br>2132A/FAL-<br>2121A/FAL-2131A<br>inside compressor<br>package |  |                          |                          |                          |                          |                          |  |                          |                                     |  |
|                                   |  | 4. Limit switch on valve   |  |                          |                          |                          |                          |                          |  |                          |                                     |  |
|                                   |  | 5. Spill back valve will open by PIC-2121A   |  |                          |                          |                          |                          |                          |  |                          |                                     |  |
|                                   |  | Internal high     temperature protection     in compressor     package                           |  |                          |                          |                          |                          |                          |  |                          |                                     |  |
| 3. XV-2121A closed by failure     | 1. Loss of suction pressure for                                | 1. PAL-2121A   |  |                          |                          |                          |                          |                          |  |                          |                                     |  |





# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

Déca Monde



شماره صفحه: 30 از 58



شماره پیمان:

 $\bullet \Delta \Psi - \bullet V \Psi - \P \, \mathsf{I} \, \mathsf{A} \, \mathsf{F}$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |        |      |
|-------------------------------------|-----------|------------|---------|------|----------|--------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سر يال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004   | D00  |

Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 1. No/Less Flow

| Causes  | Consequences  | Safeguards   | Recommendations |
|---|---|--|-----------------|
| or error (any failure inside<br>UCP)              | one compressor with possibility of damage to compressor due to over heating   | PALL-2122A that will activate ESD-2  |                 |
| PCV-2123A closed more<br>when required to be open | Low suction pressure in compressor with possibility of  | V-2101A is designed for full vacuum  |                 |
|   | vacuum formation  | 2. PAL-2121A<br>(dependent)  |                 |
|   |   | 3. PALL-2122A that will activate ESD-2   |                 |
|   |   | 4. PAL-2123A/PAL-<br>2124A/PAL-<br>2132A/FAL-<br>2121A/FAL-2131A<br>inside compressor<br>package |                 |
| 5. Plugging of demister pad                       | 1. Same as above  |  |                 |
|   | Possibility of damage to demister pad   | 1. PDAH-2121A  |                 |
| Plugging of compressor suction strainer           | Low suction pressure in<br>compressor and damage to<br>strainer   | PDIT-2122A inside compressor package   |                 |
| 7. Compressor failure or trip                     | Decreased capacity of station   | Spare compression train is considered  |                 |
|   | Increased pressure upstream     of compressor with possibility     of damage due to over     compressors leaders and fire | PSVs on V-2104 and<br>V-2105 are designed<br>for blocked outlet                                  |                 |
|   | pressure, leakage and fire  | PAHH-2122 that will activate ESD-2   |                 |

Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 2. More Flow

| Causes  | Consequences  | Safeguards   | Recommendations  |
|---|---|--|--|
| PCV-2123A open more<br>when required to be closed | High suction pressure with possibility of damage to suction, leakage and fire | 1. PAH-2124A/PAH-<br>2123A/PAH-2132A<br>inside compressor<br>package | 35. Install check valve at 2nd stage discharge, downstream of spill back branch (at min distance to XV-2133A) and install check valve at inlet to each compressor train upstream of spill back branch. |
|   |   | 2. PAHH-2122A that will activate ESD-2                               | 36. Consider limit switch for spill back valve PCV-2123A.  |
|   |   |  | 37. Study requirement to consider over pressure protection for V-  |











### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان: ۹۱۸۴ – ۰۷۳ – ۰۵۳

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |

شماره صفحه: 31 از 58

Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 2. More Flow

| Causes | Consequences   | Safeguards  | Recommendations                                    |
|--------|--|---|--|
|        |  |   | 2101 due to opening of spill back valve PCV-2123A. |
|        | 2. High suction temperature                                      | 1. TAH-2121A  |  |
|        | with possibility of damage to compressor                         | TAH-2122A inside compressor package                   |  |
|        |  | 3. TAHH-2124A that will activate ESD-2                |  |
|        |  | High temperature protection inside compressor package |  |
|        | Low 2nd stage discharge pressure and decreased capacity of train | 1. PAL-2132A  |  |

Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 3. Reverse/Misdirected Flow

| Causes                                     | Consequences | Safeguards | Recommendations |
|--|--------------|------------|-----------------|
| Check valves are considered where required |              |            |                 |

Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 4. High Temperature

| Causes                                   | Consequences                             | Safeguards                              | Recommendations                      |
|--|--|---|--------------------------------------|
| Mechanical failure in compressor package | Damage to compressor or discharge piping | TAH-2123A inside compressor package     |                                      |
|  |  | 2. TAHH-2124A that will activate ESD-2  |                                      |
| 2. Decreased flow through                | 1. Same as above                         | 1. FAL-2121A                            |                                      |
| compressor                               |  | TAH-2123A inside compressor package     |                                      |
|  |  | 3. TAHH-2124A that will activate ESD-2  |                                      |
| 3. Air cooler fan failure or trip        | 1. High temperature of 2nd               | 1. TAH-2126A                            | 38. Correct P&ID of air coolers of   |
|  | stage with possibility of damage to it   | 2. TAHH-2125A that will activate ESD-2  | compressors according to data sheet. |
|  |  | Two pairs of air coolers are considered |                                      |





# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

Déca Monde



شماره پیمان:  $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |

شماره صفحه: 32 از 58

Deviation: 5. Low Temperature

| Causes   | Consequences                                  | Safeguards   | Recommendations |
|--|---|--------------|-----------------|
| More cooling in air coolers<br>due to wrong adjustment of<br>pitch | Waste of energy with no hazardous consequence | 1. TAL-2126A |                 |

#### Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 6. High Pressure

| Causes  | Consequences        | Safeguards         | Recommendations |
|---|---------------------|--------------------|-----------------|
| External fire case for V-<br>2101A                      | Damage to equipment | 1. PSV-2121A       |                 |
| Blocked outlet for<br>compressor 1st stage<br>discharge | Damage to equipment | 1. PSV-2122A/2123A |                 |

#### Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 7. Low Pressure

| Causes                         | Consequences | Safeguards | Recommendations |
|--------------------------------|--------------|------------|-----------------|
| 1. No new issue was identified |              |            |                 |

#### Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 8. High Level

| Causes  | Consequences                          | Safeguards  | Recommendations |
|---|---------------------------------------|---|-----------------|
| XV-2122A remained closed when required to be open      Accumulation of liquid in V-2101A and carry over to compressor with possibility of the compressor with the compression with the compressor with the compressor with the compression with the compressor with the compression with the compressor with the c | 1. LAH-2121A<br>(dependent)           |   |                 |
|   | compressor with possibility of damage | LAHH-2122A that will activate ESD-2 and trip compressor   |                 |
|   |                                       | LAHH-2117 that will<br>activate ESD-3 on<br>inlet KO drum |                 |


#### Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 9. Low Level

| Causes                    | Consequences  | Safeguards  | Recommendations |
|---------------------------|---|---|-----------------|
| 1. XV-2122A remained open | Gas blowby via closed drain<br>header to flare and waste of | 1. LAL-2121A<br>(dependent)                               |                 |
|                           | gas   | 2. LALL-2122A that will activate ESD-3 and close XV-2122A |                 |
|                           | Slight decreased suction pressure of compressor             | 1. PAL-2121A  |                 |
|                           |   | 2. PAL-2123A/PAL-   |                 |











شماره پیمان: ۹۱۸۴ – ۰۷۳ – ۰۵۳

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |        |      |
|-------------------------------------|-----------|------------|---------|------|----------|--------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سر يال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004   | D00  |

شماره صفحه: 33 از 58

Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 9. Low Level

| Causes | Consequences | Safeguards  | Recommendations |
|--------|--------------|---|-----------------|
|        |              | 2124A/PAL-<br>2132A/FAL-<br>2121A/FAL-2131A<br>inside compressor<br>package |                 |
|        |              | 3. Spill back valve will open by PIC-2121A                                  |                 |

Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 10. Maintenance Hazards

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | <ol> <li>Consider block valves for N2<br/>supply lines to compressor<br/>packages.</li> </ol> |
|                       |              |            | Consider maintenance lock for fan of air coolers in data sheet.                               |

Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 11. Loss of Utilities

| Causes  | Consequences                               | Safeguards                          | Recommendations   |
|---|--|-------------------------------------|---|
| failure of electrical tracing at compressor suction | Possibility of condensation in cold season | Inspection & maintenance procedures | <ol> <li>Consider drain connection on<br/>low point of line between V-<br/>2101A and compressor.</li> </ol> |


Node: 5. 1st Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 12. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 42. General recommendation: All solenoids with signal in ESD system should have manual reset.                                   |
|                       |              |            | 43. Relocate sample connections of compressor suctions to Binak and Golkhari inlet lines and also on Inlet KO Drum outlet line. |







شماره پیمان:  $\bullet \Delta \Upsilon - \bullet V \Upsilon - \P \, \mathsf{IAF} \,$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |  |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|--|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |  |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |  |

شماره صفحه: 34 از 58

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 1. No/Less Flow

| Causes   | Consequences   | Safeguards   | Recommendations |
|--|--|--|-----------------|
| Decreased flow from upstream due to any reason | Low suction pressure with possibility of damage to                                     | PALL-2131A that will activate ESD-2  |                 |
|  | compressors due to over heating  | 2. PAL-2123A/PAL-<br>2124A/PAL-<br>2132A/FAL-<br>2121A/FAL-2131A<br>inside compressor<br>package |                 |
|  |  | 3. Spill back valve will open by PIC-2121A   |                 |
|  |  | Internal high     temperature protection     in compressor     package                           |                 |
| 2. Plugging of demister pad                    | 1. Same as above   |  |                 |
|  | Possibility of damage to demister pad  | 1. PDAH-2131A  |                 |
| Plugging of compressor suction strainer        | Low suction pressure in<br>compressor and damage to<br>strainer                        | PDIT-2132A inside compressor package   |                 |
| 4. Compressor failure or trip                  | Decreased capacity of station  | Spare compression train is considered  |                 |
|  | Increased pressure upstream<br>of compressor with possibility<br>of damage due to over | PSVs on V-2104 and<br>V-2105 are designed<br>for blocked outlet                                  |                 |
|  | pressure   | PAHH-2122 that will activate ESD-2   |                 |
| 5. XV-2133A closed by failure or error         | Blocked outlet for compressor and damage to it   | 1. PSV-2132A/2133A   |                 |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 2. More Flow

| Causes                     | Consequences | Safeguards | Recommendations |
|----------------------------|--------------|------------|-----------------|
| 1. No issue was identified |              |            |                 |


Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 3. Reverse/Misdirected Flow

| Causes                                     | Consequences | Safeguards | Recommendations |
|--|--------------|------------|-----------------|
| Check valves are considered where required |              |            |                 |









شماره صفحه: 35 از 58

شماره پیمان: · 24 - · 74 - 4 1 1 4

| HAZOP REPORT FOR COMPRESSOR STATION                          |     |       |     |    |    |      |     |
|--|-----|-------|-----|----|----|------|-----|
| نسخه سریال نوع مدر ک رشته تسهیلات صادر کننده بسته کاری پروژه |     |       |     |    |    |      |     |
| BK   | GCS | PEDCO | 120 | GE | RT | 0004 | D00 |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 4. High Temperature

| Causes                                   | Consequences  | Safeguards                              | Recommendations                      |
|--|---|---|--------------------------------------|
| Mechanical failure in compressor package | Damage to compressor or discharge piping                              | TAH-2133A inside compressor package     |                                      |
|  |   | 2. TAHH-2134A that will activate ESD-2  |                                      |
| 2. Decreased flow through                | 1. Same as above  | 1. FAL-2131A                            |                                      |
| compressor                               |   | TAH-2133A inside compressor package     |                                      |
|  |   | 3. TAHH-2134A that will activate ESD-2  |                                      |
| 3. Air cooler fan failure or trip        | 1. High temperature of 2nd  | 1. TAH-2135A                            | 38. Correct P&ID of air coolers of   |
|  | stage discharge with<br>possibility of damage to<br>downstream piping | 2. TAHH-2136A that will activate ESD-2  | compressors according to data sheet. |
|  |   | Two pairs of air coolers are considered |                                      |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 5. Low Temperature

| Causes   | Consequences                                  | Safeguards   | Recommendations |
|--|---|--------------|-----------------|
| More cooling in air coolers<br>due to wrong adjustment of<br>pitch | Waste of energy with no hazardous consequence | 1. TAL-2135A |                 |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 6. High Pressure

| Causes                             | Consequences           | Safeguards                            | Recommendations |
|------------------------------------|------------------------|---------------------------------------|-----------------|
| External fire case for V-<br>2102A | 1. Damage to equipment | 1. PSV-2131A                          |                 |
| 2. Blocked outlet for              | Damage to equipment,   | 1. PSV-2132A/2133A                    |                 |
| compressor 2nd stage discharge     | leakage and fire       | 2. PAHH-2134 that will activate ESD-2 |                 |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 7. Low Pressure

| Causes                                | Consequences  | Safeguards                             | Recommendations |
|---------------------------------------|---|--|-----------------|
| BDV-2134A open by failure<br>or error | Waste of gas to flare with environmental effect       | 1. Limit switch on valve               |                 |
|                                       | Low suction pressure for 2nd stage and possibility of | 1. PALL-2131A that will activate ESD-2 |                 |





# احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

Déca Monde Process Safety



شماره صفحه: 36 از 58

شماره پیمان: ۹۱۸۴ – ۰۷۳ – ۰۵۳

| HAZOP REPORT FOR COMPRESSOR STATION |  |       |     |    |    |      |     |
|-------------------------------------|--|-------|-----|----|----|------|-----|
| پروژه                               | نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پروژه |       |     |    |    |      |     |
| BK                                  | GCS  | PEDCO | 120 | GE | RT | 0004 | D00 |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 7. Low Pressure

| Causes  | Consequences   | Safeguards                       | Recommendations  |
|---|--|----------------------------------|--|
|   | damage to compressor due to over heating  2. Internal high temperature protect in compressor package |                                  |  |
|   | Low temperature after BDV with no hazardous consequence  |                                  |  |
| 2. BDV-2132A open by failure or error             | Waste of gas to flare with environmental effect  | 1. Limit switch on valve         |  |
|   | Low temperature after BDV with possibility of freezing   | Methanol injection is considered | 44. Provide XV with remote access for depressurizing of 1st stage suction drum of compressors to give more operability during maintenance. |
| 3. PCV-2135A open more when required to be closed | Waste of gas to flare with environmental effect  | 1. PAL-2135A<br>(dependent)      |  |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 8. High Level

| Causes   | Consequences  | Safeguards  | Recommendations |
|--|---|---|-----------------|
| XV-2131A remained closed<br>when required to be open | Accumulation of liquid in V-<br>2102A and carry over to | 1. LAH-2131A<br>(dependent)                                   |                 |
|  | compressor with possibility of damage                   | LAHH-2132A that will<br>activate ESD-2 and<br>trip compressor |                 |
|  |   | Operator will be alerted by high level alarm (recommendation) |                 |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 9. Low Level

| Causes                    | Consequences  | Safeguards  | Recommendations |
|---------------------------|---|---|-----------------|
| 1. XV-2131A remained open | Gas blowby via closed drain<br>header to flare and waste of | 1. LAL-2131A<br>(dependent)   |                 |
|                           | gas   | 2. LALL-2132A that will activate ESD-3 and close XV-2131A                 |                 |
|                           | Possibility of high pressure in closed drain drum           | Closed drain in<br>connected to flare<br>header with locked<br>open valve |                 |





#### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک





شماره پیمان: · 24 - · 74 - 9114

| HAZOP REPORT FOR COMPRESSOR STATION                        |  |  |  |  |  |  |
|--|--|--|--|--|--|--|
| نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پروژه |  |  |  |  |  |  |
| BK GCS PEDCO 120 GE RT 0004 D00                            |  |  |  |  |  |  |

شماره صفحه: 37 از 58

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 9. Low Level

| Causes | Consequences                                    | Safeguards  | Recommendations |
|--------|---|---|-----------------|
|        | Slight decreased suction pressure of compressor | 1. FAL-2131A/PAL-<br>2132A inside<br>compressor package |                 |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 10. Maintenance Hazards

| Causes                         | Consequences | Safeguards | Recommendations |
|--------------------------------|--------------|------------|-----------------|
| 1. No new issue was identified |              |            |                 |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 11. Loss of Utilities

| Causes  | Consequences                               | Safeguards                          | Recommendations  |
|---|--|-------------------------------------|--|
| failure of electrical tracing at compressor suction | Possibility of condensation in cold season | Inspection & maintenance procedures | 46. Consider drain connection on low point of line between V-2102A and compressor. |

Node: 6. 2nd Stage Gas Compression Suction Drums, Compressors and Air Coolers

Deviation: 12. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 47. Remove sample connection on suction and discharge of compressor 2nd stage. |

Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 1. No/Less Flow

| Causes   | Consequences  | Safeguards   | Recommendations |
|--|---|--|-----------------|
| 1. XV-2142 closed by failure or                      |   | 1. PSV-2141/2142                                       |                 |
| error  | compressor station and damage to equipment, fire and personnel injury | High pressure<br>safeguards on<br>compressor discharge |                 |
| XV-2143 closed by failure or<br>error during startup | Delay in startup  |  |                 |

Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 2. More Flow

| Causes                     | Consequences | Safeguards | Recommendations |
|----------------------------|--------------|------------|-----------------|
| 1. No issue was identified |              |            |                 |





### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

| پیمان: | شماره |
|--------|-------|
|        |       |

· 24 - · 74 - 4 1 1 4

| HAZOP REPORT FOR COMPRESSOR STATION                        |     |       |     |    |    |      |     |   |
|--|-----|-------|-----|----|----|------|-----|---|
| نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پروژه |     |       |     |    |    |      |     |   |
| BK   | GCS | PEDCO | 120 | GE | RT | 0004 | D00 |   |
|  |     |       |     |    |    |      |     | - |

شماره صفحه: 38 از 58

Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 3. Reverse/Misdirected Flow

| Causes                                     | Consequences | Safeguards | Recommendations |
|--|--------------|------------|-----------------|
| Check valves are considered where required |              |            |                 |

Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 4. High Pressure

| Causes                           | Consequences           | Safeguards  | Recommendations |
|----------------------------------|------------------------|-------------|-----------------|
| 1. External fire case for V-2103 | 1. Damage to equipment | 1. PSV-2141 |                 |

Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 5. Low Pressure

| Causes                                      | Consequences                                    | Safeguards                       | Recommendations   |
|---|---|----------------------------------|---|
| BDV-2141 open by failure or error           | Waste of gas to flare with environmental effect | 1. Limit switch on valve         | 48. Correct on P&ID that outlet pipe of BDV 2141 is connected directly to flare header separated from tail pipe of PSVs |
|   | 2. Possibility of freezing of line              | Methanol injection is considered |   |
| Maloperation during steam<br>out at startup | Vacuum formation and V-<br>2103 collapse        |                                  | 49. Full vacuum should be considered for design pressure of V-2103.   |

Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 6. High Level

| Causes                             | Consequences                      | Safeguards                         | Recommendations                                       |
|------------------------------------|-----------------------------------|------------------------------------|---|
| XV-2144 closed by failure or error | carry over to dehydration         | 1. LAH-2141<br>(dependent)         | 50. Show on P&ID stand pipe for LG-2141 and LIT-2141. |
|                                    | package and degradation of glycol | LAHH-2142 that will activate ESD-1 |   |

Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 7. Low Level

| Causes                      | Consequences   | Safeguards  | Recommendations  |
|-----------------------------|--|---|--|
| 1. XV-2144 remained open by | 1. Gas blowby via closed drain                       | 1. LAL-2141 (dependent)                                 |  |
| failure or error            | header to flare and waste of gas                     | 2. LALL-2142 that will activate ESD-3 and close XV-2144 |  |
|                             | Possibility of high pressure in<br>closed drain drum | Closed drain in connected to flare                      | 51. As per drain configuration, consider gate valve, spectacle |









#### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان: ۹۱۸۴ – ۰۷۳ – ۰۵۳

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |

شماره صفحه: 39 از 58

Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 7. Low Level

| Causes | Consequences | Safeguards                    | Recommendations                                    |
|--------|--------------|-------------------------------|--|
|        |              | header with locked open valve | and globe valve arrangement for bypass of XV-2144. |

#### Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 8. Maintenance Hazards

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 52. Consider spectacle blind on B2 nozzle of V-2103.  |
|                       |              |            | 53. Consider spectacle blind on corrosion inhibitor injection line to V-2103 after check valve. |

#### Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 9. Corrosion

| Causes  | Consequences                                | Safeguards  | Recommendations |
|---|---|---|-----------------|
| Corrosion due to sulphur and moisture content | Damage to equipment and piping in long term | Corrosion monitoring (CP/CC)                                    |                 |
|   |   | Corrosion inhibitor injection is considered                     |                 |
|   |   | 3. Liquid line from V-<br>2103 to XV-2144 is<br>Stainless Steel |                 |

#### Node: 7. 2nd Stage Gas Compression Discharge Drum

Deviation: 10. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 54. Show on P&ID line number and inlet reducer of XV-2143. |
|                       |              |            | 55. Remove TG-2143.  |

#### Node: 8. Gas Compression Dehydration Package

Deviation: 1. No/Less Flow

| Causes  | Consequences  | Safeguards        | Recommendations  |
|---|---|-------------------|--|
| Decreased flow to<br>downstream due to any<br>blockage in pipeline or<br>Siahmakan facilities | Increased pressure for<br>dehydration package and<br>change in operating condition<br>of it that will lead to more tail<br>gas to flare | PCV-2152 to flare | <ul><li>56. Define high alarm on PIC-<br/>2152.</li><li>57. Show dedicated control blocks<br/>for PCV-2152 and PCV-2151.</li></ul> |





### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

Déca Monde



شماره پیمان:  $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

|       | HAZOP REPORT FOR COMPRESSOR STATION |            |         |      |          |       |      |
|-------|-------------------------------------|------------|---------|------|----------|-------|------|
| پروژه | بسته کاری                           | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |
| BK    | GCS                                 | PEDCO      | 120     | GE   | RT       | 0004  | D00  |

شماره صفحه: 40 از 58

Node: 8. Gas Compression Dehydration Package

Deviation: 1. No/Less Flow

| Causes  | Consequences  | Safeguards   | Recommendations  |
|---|---|--|--|
| PCV-2151 closed more by a<br>failure in any elements of its<br>control loop | 1. Same as above  | PIC-2152 will open     PCV-2152 to flare     (dependent) |  |
|   | Blocked outlet for<br>compressor station and<br>damage to equipment, fire<br>and personnel injury | Upstream PSVs are designed for blocked outlet            | 58. Failure mode of PCV-2151 should be FC and failure mode of PCV-2152 should be FO.             |
|   |   |  | 59. Class of PCV-2151, PCV-<br>2152 and BDV-2151 should<br>be 600#.                              |
|   |   |  | 60. General recommendation: check size of control valves to be compatible with IPS requirements. |

Node: 8. Gas Compression Dehydration Package

Deviation: 2. More Flow

| Causes  | Consequences   | Safeguards                                       | Recommendations |
|---|--|--|-----------------|
| PCV-2151 open more by a failure in any elements of its control loop | Decreased pressure and<br>more flow through<br>dehydration package and<br>increased moisture in gas to<br>pipeline | Moisture analyzer inside package with high alarm |                 |

Node: 8. Gas Compression Dehydration Package

Deviation: 3. Reverse/Misdirected Flow

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 61. Consider check valve on 2" closed drain connection from dehydration package. |

Node: 8. Gas Compression Dehydration Package

Deviation: 4. High Pressure

| Causes         | Consequences        | Safeguards | Recommendations  |
|----------------|---------------------|------------|--|
| Blocked outlet | Damage to equipment |            | 62. Check with vendor requirement for sizing PSV on dehydration package for blocked outlet scenario. |





شماره صفحه: 41 از 58





### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

| HAZOP REPORT FOR COMPRESSOR STATION                         |     |       |     |    |    |      |     |
|---|-----|-------|-----|----|----|------|-----|
| نسخه سریال نوع مدرک رشته تسهیلات صادر کننده بسته کاری پروژه |     |       |     |    |    |      |     |
| BK  | GCS | PEDCO | 120 | GE | RT | 0004 | D00 |

 $\bullet \Delta \Upsilon - \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

Node: 8. Gas Compression Dehydration Package

Deviation: 5. Low Pressure

| Causes  | Consequences                                       | Safeguards               | Recommendations                       |
|---|--|--------------------------|---------------------------------------|
| BDV-2151 open by failure or error                                   | Waste of gas to flare with environmental effect    | 1. Limit switch on valve | 63. Define low alarm on PIC-<br>2152. |
| PCV-2152 open more by a failure in any elements of its control loop | Waste of gas to flare with<br>environmental effect |                          |                                       |

Node: 8. Gas Compression Dehydration Package

Deviation: 6. Corrosion

| Causes  | Consequences                                | Safeguards                                  | Recommendations   |
|---|---|---|---|
| Corrosion due to sulphur and moisture content | Damage to equipment and piping in long term | Corrosion monitoring (CP/CC)                | 64. Show on P&ID of dehydration package detail of corrosion |
|   |   | Corrosion inhibitor injection is considered | inhibitor injection valving.                                |

Node: 8. Gas Compression Dehydration Package

Deviation: 7. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 65. Equalizing valve on bypass of dehydration package should be 2" and gate valve on this bypass should be changed to ball valve. |
|                       |              |            | 66. Consider block valve of fuel gas supply line to dehydration package.  |
|                       |              |            | 67. Show on P&ID of dehydration package, BMS and min required signals to/from plant DCS and ESD.                                  |
|                       |              |            | 68. HAZOP study of dehydration package shall be performed with participation of package vendor.                                   |

Node: 9. Lean Glycol Storage Tank

Deviation: 1. No/Less Flow

| Causes                       | Consequences                               | Safeguards                 | Recommendations  |
|------------------------------|--|----------------------------|--|
| 1. P-2103A/B failure or trip | Delay in makeup glycol flow to dehydration | Standby pump is considered | 69. Correct on P&ID min flow (including RO) of P-2103A/B to be connected directly to nozzle B2 of TK-2102. |





### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

Déca Monde



شماره پیمان:

 $\bullet \Delta \Upsilon - \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

|   | HAZOP REPORT FOR COMPRESSOR STATION |  |  |  |  |     |      |
|---|-------------------------------------|--|--|--|--|-----|------|
| نسخه سریال نوع مدرک رشته تسهیلات صادر کننده بسته کاری پروژه |                                     |  |  |  |  |     | نسخه |
| BK GCS PEDCO 120 GE RT 0004 D00                             |                                     |  |  |  |  | D00 |      |

شماره صفحه: 42 از 58

Node: 9. Lean Glycol Storage Tank

Deviation: 1. No/Less Flow

| Causes | Consequences | Safeguards                | Recommendations                               |
|--------|--------------|---------------------------|---|
|        |              | 2. Intermittent operation | 70. Remove auto/manual signal from P-2103A/B. |

Node: 9. Lean Glycol Storage Tank

Deviation: 2. More Flow

| Causes                     | Consequences | Safeguards | Recommendations |
|----------------------------|--------------|------------|-----------------|
| 1. No issue was identified |              |            |                 |

Node: 9. Lean Glycol Storage Tank

Deviation: 3. Reverse/Misdirected Flow

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 71. Consider check valve on glycol line from P-2103A/B to PK-2101. |

Node: 9. Lean Glycol Storage Tank

Deviation: 4. High Pressure

| Causes  | Consequences                    | Safeguards                 | Recommendations   |
|---|---------------------------------|----------------------------|---|
| PRV-2162 open more by failure                       | Possibility of damage to tank   | 1. PVSV-2161/PVSV-<br>2162 | 72. Blanketing of TK-2102 should be with N2.                          |
|   |                                 |                            | 73. Consider safety hatch for TK-<br>2102.                            |
|   |                                 |                            | 74. Consider pressure transmitter with high and low alarm on TK-2102. |
|   |                                 |                            | 75. PVSV-2161/2162 should be vented to ATM.                           |
| PRV-2161 closed more by failure during tank filling | 1. Same as above                | 1. PVSV-2161/PVSV-<br>2162 |   |
| External fire case for TK-<br>2101                  | 1. Damage to tank               | 1. PVSV-2161/PVSV-<br>2162 |   |
| Blocked outlet for P-<br>2103A/B                    | High pressure of pump discharge | 1. Min flow is considered  |   |

Node: 9. Lean Glycol Storage Tank

Deviation: 5. Low Pressure

| Causes  | Consequences             | Safeguards         | Recommendations              |
|---|--------------------------|--------------------|------------------------------|
| PRV-2161 closed more by failure during tank level | Vacuum formation and TK- | 1. PVSV-2161/PVSV- | 76. Show vacuum set point of |



احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک







#### شماره پیمان:

 $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

|       | HAZOP REPORT FOR COMPRESSOR STATION                          |       |     |    |    |      |     |
|-------|--|-------|-----|----|----|------|-----|
| پروژه | نسخه سریال نوع مدر ک رشته تسهیلات صادر کننده بسته کاری پروژه |       |     |    |    |      |     |
| BK    | GCS  | PEDCO | 120 | GE | RT | 0004 | D00 |

شماره صفحه: 43 از 58

Node: 9. Lean Glycol Storage Tank

Deviation: 5. Low Pressure

| Causes     | Consequences  | Safeguards | Recommendations |
|------------|---------------|------------|-----------------|
| decreasing | 2102 collapse | 2162       | PVSV-2161/2162. |

Node: 9. Lean Glycol Storage Tank

Deviation: 6. High Level

| Causes                  | Consequences            | Safeguards  | Recommendations                       |
|-------------------------|-------------------------|-------------|---------------------------------------|
| Operator error and over | Over flow from tank and | 1. LAH-2162 | 77. LIT-2161 and LIT-2162 should      |
| filling of tank         | waste of material       | 2. Dike     | be readable at grade in loading area. |

Node: 9. Lean Glycol Storage Tank

Deviation: 7. Low Level

| Causes   | Consequences                                | Safeguards  | Recommendations |
|--|---|---|-----------------|
| TK-2102 not refilled at proper time due to error | Loss of fresh glycol to dehydration package | 1. LAL-2162   |                 |
|  | Possibility of damage to P-<br>2103A/B      | LALL-2161 that will activate ESD-3 and stop P-2103A/B |                 |

Node: 9. Lean Glycol Storage Tank Deviation: 8. Maintenance Hazards

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 78. Consider spectacle blind on 2" drain nozzle D of TK-2102. |

Node: 9. Lean Glycol Storage Tank

Deviation: 9. Corrosion

| Causes       | Consequences                                | Safeguards                | Recommendations |
|--------------|---|---------------------------|-----------------|
| 1. Corrosion | Damage to equipment and piping in long term | Corrosion monitoring (CC) |                 |

Node: 9. Lean Glycol Storage Tank

Deviation: 10. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 79. Remove check valve on suction of P-2103A/B.                   |
|                       |              |            | 80. Correct P&ID of glycol tank and show nozzle A at top of tank. |









### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

.04 - . 14 - 4114

|       | HAZOP REPORT FOR COMPRESSOR STATION |            |         |      |          |       |      |   |
|-------|-------------------------------------|------------|---------|------|----------|-------|------|---|
| پروژه | بسته کاری                           | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |   |
| BK    | GCS                                 | PEDCO      | 120     | GE   | RT       | 0004  | D00  |   |
|       |                                     |            |         |      |          |       |      | _ |

شماره صفحه: 44 از 58

Node: 9. Lean Glycol Storage Tank

Deviation: 10. Miscellaneous

| Causes | Consequences | Safeguards | Recommendations                         |
|--------|--------------|------------|---|
|        |              |            | 81. Consider PG on discharge of P-2102. |

Node: 10. Instrument & Plant Air System

Deviation: 1. No/Less Flow

| Deviation: 1. No/Less Flow  |   |  |  |
|---|---|--|--|
| Causes  | Consequences  | Safeguards   | Recommendations  |
| Any failure inside instrument<br>air package and<br>compressors       | and air and loss of plant control V-2203 with 15            | V-2203 with 15 min   | 82. Number, signal and set points of PTs (PT-2203) for start/stop of standby air compressor should be according to IPS requirements. |
|   |   |  | 83. ESD level on PALL-<br>2201A/B/C should be 1A.  |
|   |   | 3. PAL-2201  |  |
|   |   | 4. PALL-2202 that will activate ESD-3 and closed ESDV-2231     |  |
|   |   | 5. PAL-2203  |  |
|   |   | 6. PALL-2201A/B/C with 2003 voting that will activate ESD-1A   |  |
|   | Low pressure of plant air with no hazardous consequence     |  |  |
| PCV-2201 closed more by a failure in any elements of its control loop | Low pressure of plant air with<br>no hazardous consequence  |  | 84. PCV-2201 should be FC.   |
| ESDV-2231 closed by failure or error                                  | 1. Same as above  |  | 85. Remove ESDV-2231 and consider solenoid on PCV-2201 to close valve by ESD-3.  |
| 4. PRV-2201 closed by failure   | Low pressure of instrument<br>air and loss of plant control | PALL-2201A/B/C with<br>2003 voting that will<br>activate ESD-1 | 83. ESD level on PALL-<br>2201A/B/C should be 1A.  |

Node: 10. Instrument & Plant Air System

Deviation: 2. More Flow

| Causes                     | Consequences | Safeguards | Recommendations |
|----------------------------|--------------|------------|-----------------|
| 1. No issue was identified |              |            |                 |









### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\bullet \Delta \Upsilon - \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

| HAZOP REPORT FOR COMPRESSOR STATION                        |     |       |     |    |    |      |     |
|--|-----|-------|-----|----|----|------|-----|
| نسخه سريال نوع مدرک رشته تسهيلات صادرکننده بسته کاری پروژه |     |       |     |    |    | نسخه |     |
| BK   | GCS | PEDCO | 120 | GE | RT | 0004 | D00 |

شماره صفحه: 45 از 58

Node: 10. Instrument & Plant Air System Deviation: 3. Reverse/Misdirected Flow

| Causes                     | Consequences | Safeguards | Recommendations |
|----------------------------|--------------|------------|-----------------|
| 1. No issue was identified |              |            |                 |

Node: 10. Instrument & Plant Air System

Deviation: 4. High Pressure

| Causes  | Consequences  | Safeguards   | Recommendations |
|---|---|--|-----------------|
| 1. external fire case for V-2203                          | Damage to equipment                                 | 1. PSV-2201A/B   |                 |
| 2. PRV-2201 open by failure                               | 1. No hazardous consequence                         |  |                 |
| 3. PCV-2201 open more by a failure in any elements of its | lure in any elements of its header and possible low |  |                 |
| control loop  | pressure of instrument air<br>header                | 2. PALL-2202 that will activate ESD-3 and closed ESDV-2231 |                 |

Node: 10. Instrument & Plant Air System

Deviation: 5. Low Pressure

| Causes                             | Consequences  | Safeguards   | Recommendations |
|------------------------------------|---|--|-----------------|
| High consumption rate of plant air | Low pressure of instrument<br>air and loss of plant control | Instrument air receiver     V-2203 with 15 min     holdup  |                 |
|                                    |   | Fault alarm on package                                     |                 |
|                                    |   | 3. PAL-2201  |                 |
|                                    |   | 4. PALL-2202 that will activate ESD-3 and closed ESDV-2231 |                 |
|                                    |   | 5. PAL-2203  |                 |
|                                    |   | 6. PIC-2201 will control<br>PCV-2201                       |                 |

Node: 10. Instrument & Plant Air System

Deviation: 6. High Level

| Causes                               | Consequences                             | Safeguards                                       | Recommendations |
|--------------------------------------|--|--|-----------------|
| Accumulation of liquid in V-<br>2203 | Possibility of damage to instrumentation | Local LG-2201 may     be checked by     operator |                 |





شماره صفحه: 46 از 58

### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک



شماره پیمان:  $\bullet \Delta \Upsilon - \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |

Node: 10. Instrument & Plant Air System

Deviation: 7. Low Level

| Causes                     | Consequences            | Safeguards | Recommendations  |
|----------------------------|-------------------------|------------|--|
| Failure of mechanical trap | Waste of instrument air |            | 86. Remove mechanical trap from V-2203 and consider mechanical trap for wet air KO drum. |

Node: 10. Instrument & Plant Air System

Deviation: 8. Composition

| Causes                        | Consequences Safeguards  |   | Recommendations |
|-------------------------------|--|---|-----------------|
| Loss of performance of dryers | Increased moisture content of instrument air and damage to instrumentation | , |                 |

Node: 11. Nitrogen Generation System

Deviation: 1. No/Less Flow

| Causes  | Consequences   | Safeguards   | Recommendations            |
|---|--|--|----------------------------|
| Any failure inside Nitrogen package and compressors                         | loss of seal gas for compressor and also leakage of gas to ATM with possible | 2204 with 15 min   |                            |
|   |  | Fault alarm on package   |                            |
|   |  | 3. PAL-2213  |                            |
|   |  | PAL-2211 inside package  |                            |
|   |  | 5. PALL-2211 that will activate ESD-1                          |                            |
|   |  | Low seal pressure     protection inside     compressor package |                            |
|   | Low pressure of nitrogen for<br>utility with no hazardous<br>consequence     |  |                            |
| PCV-2211 closed more by a<br>failure in any elements of its<br>control loop | 1. Same as above   |  | 87. PCV-2211 should be FO. |

Node: 11. Nitrogen Generation System

Deviation: 2. More Flow

| Causes  | Consequences  | Safeguards | Recommendations |
|---|---|------------|-----------------|
| PCV-2211 open more by a failure in any elements of its control loop | Slightly high pressure of<br>nitrogen header with no<br>hazardous consequence |            |                 |





### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\bullet \Delta \Upsilon - \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |   |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|---|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |   |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |   |
|                                     |           |            |         |      |          |       |      | _ |

شماره صفحه: 47 از 58

Node: 11. Nitrogen Generation System Deviation: 3. Reverse/Misdirected Flow

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 88. Consider check valve on nitrogen branches to gas compressors. |

Node: 11. Nitrogen Generation System

Deviation: 4. High Pressure

| Causes                           | Consequences           | Safeguards     | Recommendations |
|----------------------------------|------------------------|----------------|-----------------|
| 1. external fire case for V-2204 | 1. Damage to equipment | 1. PSV-2211A/B |                 |

Node: 11. Nitrogen Generation System

Deviation: 5. Low Pressure

| Causes                         | Consequences | Safeguards | Recommendations |
|--------------------------------|--------------|------------|-----------------|
| 1. No new issue was identified |              |            |                 |

Node: 11. Nitrogen Generation System

Deviation: 6. High Level

| Causes                               | Consequences                             | Safeguards                                       | Recommendations |
|--------------------------------------|--|--|-----------------|
| Accumulation of liquid in V-<br>2204 | Possibility of damage to compressor seal | Local LG-2211 may     be checked by     operator |                 |

Node: 11. Nitrogen Generation System

Deviation: 7. Low Level

| Causes                        | Consequences         | Safeguards | Recommendations  |
|-------------------------------|----------------------|------------|--|
| 1. Failure of mechanical trap | 1. Waste of nitrogen |            | 89. Remove mechanical trap from V-2204 and consider mechanical trap for wet air KO drum inside compressor package. |

Node: 11. Nitrogen Generation System

Deviation: 8. Composition

| Causes                     | Consequences  | Safeguards                                       | Recommendations                               |
|----------------------------|---|--|---|
| Loss of performance of PSA | Increased moisture/oxygen<br>content of nitrogen and<br>damage to compressor seal | Moisture analyzer inside package with high alarm | 90. Remove HC analyzer from nitrogen package. |
|                            |   | 2. oxygen analyzer                               |   |





### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

| :        | پیمان | شماره |
|----------|-------|-------|
| . ^~ ~ _ | 9116  |       |

|                                 | HAZOP REPORT FOR COMPRESSOR STATION                        |  |  |  |  |  |     |
|---------------------------------|--|--|--|--|--|--|-----|
| پروژه                           | نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پروژه |  |  |  |  |  |     |
| BK GCS PEDCO 120 GE RT 0004 D00 |  |  |  |  |  |  | D00 |

شماره صفحه: 48 از 58

Node: 11. Nitrogen Generation System

Deviation: 8. Composition

| Causes | Consequences | Safeguards                        | Recommendations |
|--------|--------------|-----------------------------------|-----------------|
|        |              | inside package with<br>high alarm |                 |

Node: 12. Closed Drain System

Deviation: 1. Reverse/Misdirected Flow

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 91. Consider check valve on 2" line from P-2201A/B to existing burn pit. |
|                       |              |            | 92. Remove 2" line connection from closed drain drum to oily water sump. |

Node: 12. Closed Drain System Deviation: 2. High Pressure

| Causes   | Consequences | Safeguards | Recommendations   |
|--|--------------|------------|---|
| No issue since V-2202 is<br>connected to flare header<br>with LO valve |              |            | 93. Globe valve on flare nozzle of V-2202 should be changed to ball type. |

Node: 12. Closed Drain System

Deviation: 3. Low Pressure

| Causes                                      | Consequences                             | Safeguards Recommendations  94. Full vacuum should be |   |
|---|--|---|---|
| Maloperation during steam<br>out at startup | Vacuum formation and V-<br>2202 collapse |   | 94. Full vacuum should be considered for design pressure of V-2202. |

Node: 12. Closed Drain System

Deviation: 4. High Level

| <u>-</u>  |   |  |   |  |  |
|---|---|--|---|--|--|
| Causes  | Consequences                              | Safeguards   | Recommendations   |  |  |
| Accumulation of liquid in V-<br>2202                            | Carry over of liquid to flare     KO drum | LIC-2221 will start 1st<br>pump on H1 setpoint<br>and 2nd pump on H2 |   |  |  |
|   |   | 2. LAH-2221  |   |  |  |
| Accumulation of surface     water/rain in closed drain     sump | Damage to equipment in sump               | LIC-2222A/B will start<br>sump pump                                  | 95. LIT-2223A/B should be float<br>type and consider only one<br>common LT for P-2203A/B. |  |  |





شماره صفحه: 49 از 58

### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک



شماره پیمان:  $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

| HAZOP REPORT FOR COMPRESSOR STATION |  |  |  |  |  |     |  |
|-------------------------------------|--|--|--|--|--|-----|--|
| پروژه                               | نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پروژه |  |  |  |  |     |  |
| BK GCS PEDCO 120 GE RT 0004 D00     |  |  |  |  |  | D00 |  |

Node: 12. Closed Drain System

Deviation: 5. Low Level

| Causes   | Consequences      | Safeguards  | Recommendations   |
|--|-------------------|---|---|
| Pump remained in service     when not required | 1. Damage to pump | PALL-2222A/B that<br>will activate ESD-3<br>and stop pump | 96. Relocate PALL-2222A/B to between pumps P-2202A/B and suction strainers. |
|  |                   | 2. LAL-2221   |   |

Node: 12. Closed Drain System Deviation: 6. Maintenance Hazards

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 97. Consider spectacle blind on inlet and outlet of P-2201A/B. |

Node: 12. Closed Drain System Deviation: 7. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 98. Relocate PIT-2252 (currently PIT-2222A) from closed drain drum to flare KO drum. |
|                       |              |            | 99. valves down stream of P-<br>2202A/B to V-2104 should be<br>LO.                   |
|                       |              |            | 100. Consider PG at discharge of P-2202A/B.  |

Node: 13. Corrosion Inhibitor Package

Deviation: 1. Loss of Performance

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 101. Consider remote stop for corrosion inhibitor package (XSP corrected to HSP). |

Node: 14. Methanol Injection Package

Deviation: 1. Loss of Performance

| Causes                        | Consequences | Safeguards | Recommendations |
|-------------------------------|--------------|------------|-----------------|
| No HAZOP issue was identified |              |            |                 |





شماره صفحه: 50 از 58

#### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

Déca Monde Process Safety



|  | پیمان:   | شماره |
|--|----------|-------|
|  | <br>4446 |       |

| HAZOP REPORT FOR COMPRESSOR STATION                         |  |  |  |  |  |  |      |  |
|---|--|--|--|--|--|--|------|--|
| نسخه سریال نوع مدرک رشته تسهیلات صادر کننده بسته کاری پروژه |  |  |  |  |  |  | نسخه |  |
| BK GCS PEDCO 120 GE RT 0004 D00                             |  |  |  |  |  |  | D00  |  |

Node: 15. LP Flare System Deviation: 1. No/Less Flow

| Causes                          | Consequences                                  | Safeguards                  | Recommendations                                       |
|---------------------------------|---|-----------------------------|---|
| 1. No/less flow of fuel gas for | Pilot flame-off and possibility               | 1. Pilot status indication  | 102. Check coverage of CCTV                           |
| pilots due to any reason        | of dispersion of flammable/toxic gas at flare | 2. LPG bottle               | and if required consider CCTV for flare monitoring in |
|                                 | tip   | 3. Auto ignition for pilots | control room.   |

Node: 15. LP Flare System Deviation: 2. More Flow

| Causes   | Consequences  | Safeguards                  | Recommendations |
|--|---|-----------------------------|-----------------|
| Flare system is designed for<br>Max flare scenario |   |                             |                 |
| 2. More flow of fuel gas for                       | Pilot flame-out and possibility     of dispersion of     flammable/toxic gas at flare | Pilot status indication     |                 |
| pilots due to any reason                           |   | 2. LPG bottle               |                 |
|  |   | 3. Auto ignition for pilots |                 |

Node: 15. LP Flare System

Deviation: 3. Reverse/Misdirected Flow

| Causes                                     | Consequences | Safeguards | Recommendations |
|--|--------------|------------|-----------------|
| Check valves are considered where required |              |            |                 |

Node: 15. LP Flare System Deviation: 4. High Pressure

| Causes            | Consequences  | Safeguards   | Recommendations |
|-------------------|---|--|-----------------|
| Emergency flaring | Pressurizing of flare header<br>and problem for operation of<br>PSVs due to back pressure | flare system is<br>designed for max back<br>pressure |                 |

Node: 15. LP Flare System Deviation: 5. Low Pressure

|      | Causes                  | Consequences | Safeguards | Recommendations |
|------|-------------------------|--------------|------------|-----------------|
| 1. [ | No issue was identified |              |            |                 |

Node: 15. LP Flare System Deviation: 6. High Level

| Causes                        | Consequences                     | Safeguards                 | Recommendations |
|-------------------------------|----------------------------------|----------------------------|-----------------|
| 1. Accumulation of liquids in | 1. Carry over of liquid to stack | 1. LIC-2251 will start 1st |                 |
| flare KO drum due to          | and damage to it and also        | pump on H1 setpoint        |                 |





شماره صفحه: 51 از 58

### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

| Déca Monde     | HIRG |
|----------------|------|
| Process Safety |      |

| N |  |
|---|--|
| 1 |  |

شماره پیمان:  $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

|       | HAZOP REPORT FOR COMPRESSOR STATION |            |         |      |          |       |      |
|-------|-------------------------------------|------------|---------|------|----------|-------|------|
| پروژه | بسته کاری                           | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |
| BK    | GCS                                 | PEDCO      | 120     | GE   | RT       | 0004  | D00  |

Node: 15. LP Flare System Deviation: 6. High Level

| Causes        | Consequences                    | Safeguards  | Recommendations |
|---------------|---------------------------------|---|-----------------|
| process upset | possibility of personnel injury | and 2nd pump on H2  |                 |
|               |                                 | 2. LAHH-2252A/B/C that will activate ESD-1 on 2003 voting |                 |

Node: 15. LP Flare System Deviation: 7. Low Level

| Causes   | Consequences      | Safeguards  | Recommendations                                       |
|--|-------------------|---|---|
| P-2201A/B remain in service<br>when not required | 1. Damage to pump | LAL-2251 will stop<br>pump (dependent)                  | 103. Relocate PALL-2251A/B to between pumps P-2201A/B |
|  |                   | LALL-2253 that will activate ESD-3 and stop pumps       | and suction strainers.                                |
|  |                   | 3. PALL-2251A/B that will activate ESD-3 and stop pumps |   |

Node: 15. LP Flare System

Deviation: 8. Maintenance Hazards

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 104. Consider spectacle blinds on suction and discharge isolation valves of P-2201A/B.                            |
|                       |              |            | 105. Define in operating manual that operator should ensure that always one discharge route of P-2201A/B is open. |

Node: 16. Oily Water Sewer Deviation: 1. High Level

| Causes                        | Consequences  | Safeguards  | Recommendations                               |
|-------------------------------|---|-------------|---|
| Accumulation of water in sumo | Over flow from sump to open<br>ditch with environmental<br>effect | 1. LAH-2273 | 106. LIT-2273 should be float type with cage. |

Node: 17. Fuel Gas System Deviation: 1. No/Less Flow

| Causes                 | Consequences                    | Safeguards  | Recommendations |
|------------------------|---------------------------------|-------------|-----------------|
| 1. ESDV-2272 closed by | 1. Loss of fuel gas and loss of | 1. PAL-2272 |                 |





شماره صفحه: 52 از 58

#### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

Déca Monde



شماره پیمان:  $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

|  | HAZOP REPORT FOR COMPRESSOR STATION |       |     |    |    |      |     |
|--|-------------------------------------|-------|-----|----|----|------|-----|
| نسخه سریال نوع مدر ک رشته تسهیلات صادر کننده بسته کاری پروژه |                                     |       |     |    |    |      |     |
| BK   | GCS                                 | PEDCO | 120 | GE | RT | 0004 | D00 |

Node: 17. Fuel Gas System Deviation: 1. No/Less Flow

| Deviation. 1. No/Less Flow  |  |   |   |  |  |
|---|--|---|---|--|--|
| Causes  | Consequences   | Safeguards                                | Recommendations   |  |  |
| failure or error  | operating glycol regeneration  | 2. Limit switch on valve                  |   |  |  |
|   | 2. Loss of fuel gas to flare pilots                                  | 1. LPG bottle                             |   |  |  |
|   | Loss of flare sweep gas and possibility of flame back to flare stack | Molecular seal is considered for flare    |   |  |  |
| PCV-2272 closed more by a<br>failure in any elements of its<br>control loop | 1. Same as above   | 1. PAL-2272<br>(dependent)                | 107. Define low alarm on PI-2271.   |  |  |
| 3. PRV-2272 closed by failure   | Loss of flare sweep gas and possibility of flame back to flare stack | Molecular seal is<br>considered for flare | 108. Replace PRV-2272 with local flow gauge, ball valve, check valve and globe valve. |  |  |
| 4. Plugging of demister   | Low pressure of fuel gas<br>system                                   |   | 107. Define low alarm on PI-2271.   |  |  |

Node: 17. Fuel Gas System Deviation: 2. More Flow

| Causes  | Consequences             | Safeguards  | Recommendations |
|---|--------------------------|-------------|-----------------|
| PCV-2272 open more by a<br>failure in any elements of its<br>control loop | No hazardous consequence | 1. PAH-2272 |                 |

Node: 17. Fuel Gas System

Deviation: 3. Reverse/Misdirected Flow

| Causes                                     | Consequences | Safeguards | Recommendations |
|--|--------------|------------|-----------------|
| Check valves are considered where required |              |            |                 |

Node: 17. Fuel Gas System Deviation: 4. High Pressure

| Causes                           | Consequences        | Safeguards     | Recommendations                                   |
|----------------------------------|---------------------|----------------|---|
| 1. external fire case for V-2205 | Damage to equipment | 1. PSV-2271A/B | 109. PSV on V-2205 should be sized for fire case. |

Node: 17. Fuel Gas System Deviation: 5. Low Pressure

| Causes                                      | Consequences                             | Safeguards | Recommendations  |
|---|--|------------|--|
| Maloperation during steam<br>out at startup | Vacuum formation and V-<br>2205 collapse |            | 110. Full vacuum should be considered for design pressure of V-2205. |



احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک







#### شماره پیمان:

 $\bullet \Delta \Upsilon - \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

| HAZOP REPORT FOR COMPRESSOR STATION                        |     |       |     |    |    |      |     |
|--|-----|-------|-----|----|----|------|-----|
| نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پروژه |     |       |     |    |    | نسخه |     |
| BK   | GCS | PEDCO | 120 | GE | RT | 0004 | D00 |

شماره صفحه: 53 از 58

Node: 17. Fuel Gas System Deviation: 6. High Level

| Causes                                    | Consequences                         | Safeguards  | Recommendations |
|---|--------------------------------------|---|-----------------|
| 1. Accumulation of liquid in V-           | Carry over of liquid to fuel         | 1. LAH-2271   |                 |
| 2205 due to carry over from inlet KO drum | gas header and disturbance for users | 2. LIC-2271 will open XV-2271                             |                 |
|   |                                      | 3. LAHH-2272 that will activate ESD-3 and close ESDV-2272 |                 |

Node: 17. Fuel Gas System

Deviation: 7. Low Level

| Causes                   | Consequences                     | Safeguards  | Recommendations |
|--------------------------|----------------------------------|---|-----------------|
| 1. XV-2271 remained open | 1. Gas blowby via closed drain   | 1. LAL-2271 (dependent)                                 |                 |
|                          | header to flare and waste of gas | 2. LIC-2271 will close<br>XV-2271 (dependent)           |                 |
|                          |                                  | 3. LALL-2272 that will activate ESD-3 and close XV-2271 |                 |

Node: 17. Fuel Gas System

Deviation: 8. Corrosion

| Causes  | Consequences                                | Safeguards                                  | Recommendations |
|---|---|---|-----------------|
| Corrosion due to sulphur and moisture content | Damage to equipment and piping in long term | Corrosion monitoring (CP/CC)                |                 |
|   |   | Corrosion inhibitor injection is considered |                 |

Node: 17. Fuel Gas System

Deviation: 9. Composition

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 111. Note in duty spec of dehydration package that requirement for fuel gas filter should be checked by vendor. |











### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\bullet \Delta \Upsilon = \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

|  | HAZOP REPORT FOR COMPRESSOR STATION |  |  |  |  |      |     |
|--|-------------------------------------|--|--|--|--|------|-----|
| نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پروژه |                                     |  |  |  |  | نسخه |     |
| BK GCS PEDCO 120 GE RT 0004 D00                            |                                     |  |  |  |  |      | D00 |

شماره صفحه: 54 از 58

Node: 17. Fuel Gas System Deviation: 10. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 112. Remove fuel gas lines used for blanketing of TK-2102 and V-2107. |

Node: 18. Diesel Oil System Deviation: 1. No/Less Flow

| Causes                     | Consequences                          | Safeguards                | Recommendations   |
|----------------------------|---------------------------------------|---------------------------|---|
| 1. P-2206A failure or trip | No flow to PK-2207 or fire water pump | Intermittent operation    |   |
| 2. P-2206B failure or trip | 1. No flow to diesel generator        | 1. Intermittent operation |   |
| 3. Plugging of strainer    | Possibility of damage to pump         | Intermittent operation    | 113. Remove PT-2281A/B from suction of P-2206A/B and consider local pressure gauge. |
|                            |                                       |                           | 114. Define high high and low low trip interlock on LI-2281A/B to trip P-2206A/B.   |

Node: 18. Diesel Oil System Deviation: 2. More Flow

| Causes                     | Consequences | Safeguards | Recommendations |
|----------------------------|--------------|------------|-----------------|
| 1. No issue was identified |              |            |                 |

Node: 18. Diesel Oil System

Deviation: 3. Reverse/Misdirected Flow


| Causes                                     | Consequences | Safeguards | Recommendations |
|--|--------------|------------|-----------------|
| Check valves are considered where required |              |            |                 |

Node: 18. Diesel Oil System Deviation: 4. Low Temperature

| Causes                     | Consequences | Safeguards | Recommendations |
|----------------------------|--------------|------------|-----------------|
| 1. No issue was identified |              |            |                 |









شماره پیمان: ۹۱۸۴ – ۰۷۳ – ۰۵۳

| HAZOP REPORT FOR COMPRESSOR STATION                         |  |  |  |  |  |  |     |
|---|--|--|--|--|--|--|-----|
| نسخه سریال نوع مدرک رشته تسهیلات صادر کننده بسته کاری پروژه |  |  |  |  |  |  |     |
| BK GCS PEDCO 120 GE RT 0004 D00                             |  |  |  |  |  |  | D00 |

شماره صفحه: 55 از 58

Node: 18. Diesel Oil System Deviation: 5. High Pressure

| Causes                           | Consequences     | Safeguards     | Recommendations |
|----------------------------------|------------------|----------------|-----------------|
| Blocked in and thermal expansion | Damage to piping | 1. TSV-2281A/B |                 |

Node: 18. Diesel Oil System Deviation: 6. High Level

| Causes                                   | Consequences                              | Safeguards     | Recommendations   |
|--|---|----------------|---|
| Over filling of vessel by operator error | Over flow from vent and waste of material | 1. LAH-2281A/B | 115. Any surface contamination on diesel oil drum area should be directed to oily water header. |

Node: 18. Diesel Oil System Deviation: 7. Low Level

| Causes                      | Consequences                | Safeguards                | Recommendations |
|-----------------------------|-----------------------------|---------------------------|-----------------|
| Tank not refilled at proper | Delay in filling daily tank | 1. Intermittent operation |                 |
| time by error               |                             | 2. LAL-2281A/B            |                 |

Node: 18. Diesel Oil System Deviation: 8. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 116. Remove steam out connection for V-2206A/B.   |
|                       |              |            | 117. Relocate globe valve at discharge of P-2206A/B to downstream of tank filling branch. |
|                       |              |            | 118. Consider drain connection at suction and discharge of P-2206A/B.                     |

Node: 19. Potable Water System
Deviation: 1. Loss of Performance

| Causes                | Consequences | Safeguards | Recommendations                       |
|-----------------------|--------------|------------|---------------------------------------|
| 1. See Recommendation |              |            | 119. Remove ESD-1 signal from P-2209. |





شماره صفحه: 56 از 58

### Déca Monde





### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:  $\bullet \Delta \Upsilon - \bullet V \Upsilon - 91 \Lambda \Upsilon$ 

| HAZOP REPORT FOR COMPRESSOR STATION                         |     |       |     |    |    |      |     |
|---|-----|-------|-----|----|----|------|-----|
| نسخه سریال نوع مدرک رشته تسهیلات صادر کننده بسته کاری پروژه |     |       |     |    |    |      |     |
| BK  | GCS | PEDCO | 120 | GE | RT | 0004 | D00 |

Node: 20. Glycol Sump Drum Deviation: 1. No/Less Flow

| Causes                    | Consequences                             | Safeguards             | Recommendations                                      |
|---------------------------|--|------------------------|--|
| 1. P-2104 failure or trip | Delay in transferring glycol from V-2107 | Intermittent operation | 120. Remove start signal from LT-<br>2293 on P-2104. |
|                           |  | 2. LAH-2293            | 121. Consider proper type for LIT-<br>2293.          |

Node: 20. Glycol Sump Drum

Deviation: 2. Reverse/Misdirected Flow

| Causes                                     | Consequences | Safeguards | Recommendations |
|--|--------------|------------|-----------------|
| Check valves are considered where required |              |            |                 |

Node: 20. Glycol Sump Drum Deviation: 3. High Pressure

| Causes  | Consequences        | Safeguards | Recommendations   |
|---|---------------------|------------|---|
| 1. PRV-2291 open by failure   | 1. Damage to V-2107 |            | 122. Consider PSV on V-2207 sized for regulator failure and fire case scenario. |
| 2. External fire case for V-2107                                    | Damage to equipment |            | 122. Consider PSV on V-2207 sized for regulator failure and fire case scenario. |
| PRV-2292 closed by failure<br>when level in V-2107 is<br>increasing | 1. Damage to V-2107 |            | 123. Consider PT with high alarm on V-2107.                                     |

Node: 20. Glycol Sump Drum Deviation: 4. Low Pressure

| Causes  | Consequences  | Safeguards | Recommendations  |
|---|---|------------|--|
| Maloperation during steam<br>out at startup                         | Vacuum formation and V-<br>2107 collapse                |            | 124. Full vacuum should be considered for design pressure of V-2107. |
| PRV-2291 closed by failure<br>when level in V-2107 is<br>decreasing | Possibility of vacuum formation and damage to equipment |            |  |

Node: 20. Glycol Sump Drum Deviation: 5. High Level

| Causes                               | Consequences  | Safeguards  | Recommendations |
|--------------------------------------|---|-------------|-----------------|
| Accumulation of liquid in V-<br>2107 | Over filling of vessel and carry over of glycol to vent | 1. LAH-2293 |                 |











### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\cdot$  DT -  $\cdot$  VT - 9 1 AF

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       |      |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |

شماره صفحه: 57 از 58

Node: 20. Glycol Sump Drum

Deviation: 6. Low Level

| Causes            | Consequences      | Safeguards            | Recommendations |
|-------------------|-------------------|-----------------------|-----------------|
|                   | 1. Damage to pump | 1. LAL-2293 that will |                 |
| when not required |                   | stop pump             |                 |

Node: 20. Glycol Sump Drum

Deviation: 7. Maintenance Hazards

| Causes                | Consequences | Safeguards | Recommendations   |
|-----------------------|--------------|------------|---|
| 1. See Recommendation |              |            | 125. Consider isolation valve downstream of PRV-2291.   |
|                       |              |            | 126. Consider spectacle on inlet and outlet lines (nozzle A, nozzle B and pump outlet) of V-2107. |
|                       |              |            | 127. Consider drain connection under V-2107.  |
|                       |              |            | 128. Consider slop for V-2107 towards pump side.  |

Node: 20. Glycol Sump Drum

Deviation: 8. Composition

| Causes                | Consequences                                   | Safeguards | Recommendations  |
|-----------------------|--|------------|--|
| Off spec spent glycol | Contamination of glycol in dehydration package |            | 129. Consider connection from P-<br>2104 to oily water system. |

Node: 20. Glycol Sump Drum

Deviation: 9. Miscellaneous

| Causes                | Consequences | Safeguards | Recommendations  |
|-----------------------|--------------|------------|--|
| 1. See Recommendation |              |            | 130. ESD level on P-2104 should be ESD-1A.                                       |
|                       |              |            | 131. Consider connection for loading spent glycol to truck downstream of P-2104. |









شماره صفحه: 58 از 58



### احداث ردیف تراکم گاز در ایستگاه جمع آوری بینک

شماره پیمان:

 $\bullet \Delta \mathtt{W} - \bullet \mathtt{V} \mathtt{W} - \mathtt{Q} \, \mathtt{IAF}$ 

| HAZOP REPORT FOR COMPRESSOR STATION |           |            |         |      |          |       | 1    |   |
|-------------------------------------|-----------|------------|---------|------|----------|-------|------|---|
| پروژه                               | بسته کاری | صادر کننده | تسهيلات | رشته | نوع مدرك | سريال | نسخه | 1 |
| BK                                  | GCS       | PEDCO      | 120     | GE   | RT       | 0004  | D00  |   |
|                                     |           |            |         |      |          |       |      |   |

#### 8.6 APPENDIX F - MARKED-UP P&IDS

