









عمومي و مشترك

شماره پیمان:

.04 - .14 - 9114

	HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION								
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه		
BK	BK SSGRL PEDCO 110 GE RT 0004 D00								

شماره صفحه: 1 از 17

طرح نگهداشت و افزایش تولید ۲۷ مخزن

HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION

نگهداشت و افزایش تولید میدان نفتی بینک

D00 JUL. 2 Rev. Dat		IFI Purpose of Issue/Status	A.Baghaei Prepared by:	M.Fakharian Checked by:	M.Mehrshad Approved by:	CLIENT Approval
D00 JUL. 2	2021	IFI	A.Baghaei	M.Fakharian	M.Mehrshad	

Status:

IDC: Inter-Discipline Check IFC: Issued For Comment IFA: Issued For Approval AFD: Approved For Design AFC: Approved For Construction AFP: Approved For Purchase AFQ: Approved For Quotation IFI: Issued For Information AB-R: As-Built for CLIENT Review

AB-A: As-Built -Approved



عمومی و مشترک







شماره صفحه: 2 از 17



شماره پیمان:

 $\cdot \Delta \Upsilon - \cdot V \Upsilon - 91 \Lambda \Upsilon$

HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION

بسته کاری صادر کننده نسخه پروژه رشته تسهيلات نوع مدرك سريال BK SSGRL PEDCO 0004 D00 110 GE RT

REVISION RECORD SHEET

PAGE	D00	D01	D02	D03	D04
1	Х				
2	X				
3	X				
4	X				
5	X X X				
6	X				
	\ \frac{\lambda}{\times}				
<u>8</u> 9	X X X X				
10	X				
11	X				
12	Χ				
13					
14	X X X				
15	X				
16	X				
17	X				
18					
19					
20	+				
21	+				
22 23					
24					
25					
26					
27					
28					
29					
30					
31					
32					
33					
34					
35					
36 37					
38					
39					
40					
41					
42					
43					
44	1				
45					
46	+				
47					
48	+				
49 50	1				
50 51					
52	1				
53					
54					
55					
56					
57	1				
58					
59	+				
60	+				
61	+				
62 63					
64	1				
65				 	

PAGE	D00	D01	D02	D03	D04
66					
67 68					
69					
70					
71					
72					
73 74					
75					
76					
77					
78 79					
80					
81					
82					
83 84			<u> </u>		
85					
86					
87					
88					
89 90					
91					
92					
93					
94					
95 96					
97					
98					
99					
100 101					
102					
103					
104					
105 106					
107					
108					
109					
110	 				
111 112					
113					
114	ļ				ļ
115	-				-
116 117			1		
118	<u> </u>				
119					
120	-				-
121 122	 		1	1	
122	t				t
124					
125					
126	-				-
127	-				-
128 129	<u> </u>				<u> </u>
130					











عمومی و مشترک

شماره پیمان:

.04 - . 14 - 4114

	HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION								
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه		
BK	SSGRL	PEDCO	110	GE	RT	0004	D00		

شماره صفحه: 3 از 17

CONTENTS

1.0	INTRODUCTION	4
2.0	SCOPE	4
3.0	NORMATIVE REFERENCES	
3.1 3.2	International Codes and Standards	5 5
4.0	PURPOSE	
5.0	HAZOP STUDY OVERVIEW	5
6.0	PROCEDURE	6
7.0	HAZOP OUTCOMES	7
8.0	ATTACHMENTS	_
8.1	Appendix A –Team Members	8
8.1	APPENDIX B – DRAWINGS LIST	10
8.1	APPENDIX C – NODES LIST	11
8.1	APPENDIX D – RECOMMENDATIONS LIST	12
8.1	Appendix E – HAZOP Worksheets	13
8.1	APPENDIX F – MARKED-UP P&IDS	17





شماره صفحه: 4 از 17







عمومی و مشترک

شماره پیمان:

· 24 - · 74 - 9114

	HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION							
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه	
BK SSGRL PEDCO 110 GE RT 0004 D00								

1.0 INTRODUCTION

Binak oilfield in Bushehr province is a part of the southern oilfields of Iran, is located 20 km northwest of Genaveh city.

With the aim of increasing production of oil from Binak oilfield, an EPC/EPD Project has been defined by NIOC/NISOC and awarded to Petro Iran Development Company (PEDCO). Also, PEDCO (as General Contractor) has assigned the EPC-packages of the Project to "Hirgan Energy - Design and Inspection" JV.

As a part of the Project, construction of well location, access road, wellhead facilities (with electric power supply) for W007S shall be done. In addition, construction of new flowline from aforementioned well location to Binak B/C unit (with extension of relevant manifold) are in the Project scope of work.

GENERAL DEFINITION

The following terms shall be used in this document.

CLIENT: National Iranian South Oilfields Company (NISOC)

Binak Oilfield Development - Construction of Well PROJECT:

> Location, Wellhead Facilities, Electrification Facilities, Flowlines for W007S and Extension of Binak B/C

Manifold

EPD/EPC CONTRACTOR (GC): Petro Iran Development Company (PEDCO)

EPC CONTRACTOR: Joint Venture of: Hirgan Energy - Design &

Inspection(D&I) Companies

VENDOR: The firm or person who will fabricate the equipment or

material.

EXECUTOR: Executor is the party which carries out all or part of

construction and/or commissioning for the project.

The firm appointed by EPD/EPC CONTRACTOR (GC) THIRD PARTY INSPECTOR (TPI):

and approved by CLIENT (in writing) for the inspection

of goods.

SHALL: Is used where a provision is mandatory. SHOULD: Is used where a provision is advisory only.

Is normally used in connection with the action by WILL:

CLIENT rather than by an EPC/EPD CONTRACTOR,

supplier or VENDOR.

Is used where a provision is completely discretionary. MAY:

2.0 **SCOPE**

The scope of HAZOP study covers all P&IDs for Extension of Binak B/C Manifold. The list of











عمومي و مشترك

شماره پیمان:

· ۵۳ - · ۷۳ - 9 1 A F

HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION							
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه
BK SSGRL PEDCO 110 GE RT 0004 D00							

شماره صفحه: 5 از 17

P&IDs is presented in appendix B.

3.0 NORMATIVE REFERENCES

3.1 INTERNATIONAL CODES AND STANDARDS

IEC 61882:2016 Hazard and Operability studies (HAZOP Studies) –
 Application guide

3.2 THE PROJECT DOCUMENTS

BK-GNRAL-HD-000-PR-DB-0001-D05
 Process Basis of Design

4.0 PURPOSE

The purpose of this document is to provide the results of "HAZOP Study" for **Binak Oilfield Development – Extension of Binak B/C Manifold**.

The objective of HAZOP study is to perform and achieve the following tasks and goals as far as practicable given the latest piping and instrumentation diagrams (P&ID's) to identify any potential hazards associated with the system and its utility systems:

- To identify any potential operating difficulties,
- Examine the effectiveness of those measures already incorporated in the design to mitigate the frequency and/or consequences of such hazards;
- To raise action items for addressing those hazards that the present design does not satisfactorily address.

5.0 HAZOP STUDY OVERVIEW

Meeting was conducted in one session at June 25, 2022 held in Neyshekar Hotel main meeting hall, Ahvaz.

A team comprising of experts from different disciplines of National Iranian South Oilfields Company (NISOC), Petro Iran Development Company (PEDCO) and Hirgan Energy Company conducted the study with a third-party HAZOP Chairman and Scribe. The list of team members is presented in appendix A.



عمومی و مشترک







شماره پیمان:

.04 - .14 - 4114

HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION							
کننده بسته کاری پروژه	نسخه سریال نوع مدرک رشته تسهیلات صادرکننده بسته کاری پر						
BK SSGRL PE	DCO 110	GE	RT	0004	D00		

شماره صفحه: 6 از 17

6.0 PROCEDURE

The review methodology will be the "Guide Word" HAZOP technique and will be performed in accordance with the guidelines published by the Center for Chemical Process Safety (CCPS) of the American Institute of Chemical Engineers (AIChE) and also noted in IEC 61882.

The purpose of the review should not be only to resolve the action items but also to identify credible deviations from the design intent. The method identifies hazards and postulates possible accident sequences resulting from such hazards; Innovative thinking then identifies the consequences of these scenarios. The process demonstrates to the Owner/Management that prudent steps which have been taken to provide a safe installation and operation.

The scope of the HAZOP shall be therefore, on identifying potential process hazards or operability concerns, not on finding solutions to reduce or eliminate these concerns. Attempting to solve problems by the HAZOP team can result in a long and inefficient study process. At the same time, the HAZOP study cannot be intended as a review of Project Design Basis and Operating Philosophies, since these must be considered as resolved when the HAZOP study will be carried out.

Each system or equipment should be divided into subsystems by consensus of the review team. The selected system shall be identified by a study node numbers and for easy reference a color code can also be inserted on the related P&ID prior to the review and worksheet during the review.

List of possible parameters and guidewords

Deviations	Guide Word	Parameter
No/Less Flow	No/Less	Flow
More Flow	More	Flow
Reverse/Misdirected Flow	Reverse/Misdirected	Flow
High Temperature	High	Temperature
Low Temperature	Low	Temperature
High Pressure	High	Pressure
Low Pressure	Low	Pressure
High Level	High	Level
Low Level	Low	Level
Maintenance Hazards	Other than	Maintenance
Leakage	As well as	Flow
Corrosion	As well as	Operation
Composition	As well as	Composition
Start-up/Shutdown Hazards	Other than	Start-up/Shutdown
Loss of Utilities	Other than	Operation









عمومي و مشترك

شماره پیمان:

 \cdot Δ T - \cdot VT - 9 1 Λ F

	HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION						
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سر يال	نسخه
BK	SSGRL	PEDCO	110	GE	RT	0004	D00

شماره صفحه: 7 از 17

Deviations	Guide Word	Parameter
Miscellaneous	As well as	Operation

7.0 HAZOP OUTCOMES

Only one node is considered for the study which is presented in appendix C. A total of 13 recommendations were obtained which are shown in appendix D. The recommendations are categorized in two groups, namely OPEN and CLOSED.

Closed recommendations are those that the team have arrived at a consensus that it is required to be done. A total of 12 closed recommendation were obtained in the meetings. Open recommendations are those that need more information from vendor for the final decision. One open recommendation was proposed during the meetings.

Appendix E consists of detailed HAZOP Worksheets of the study.



عمومی و مشترک



شماره صفحه: 8 از 17

ىيمان:	شماده
ييس.	سسارت

 $\bullet \Delta T - \bullet V T - 91 \Lambda F$

HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION										
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه			
BK	SSGRL	PEDCO	110	GE	RT	0004	D00			
								-		

8.0 ATTACHMENTS

8.1 APPENDIX A –TEAM MEMBERS

First Name	Last Name	Company	Expertise
S.Mehdi	Ashrafian	NISOC	Project Manager
Shamsolah	Bahadori	NISOC	Construction Manager
Fatemeh	Ghodsi	NISOC	Head of I&C
Mohammad	Torfi	NISOC	Process
Sahar	Saba	NISOC	Process
Niloofar	Rezaei Baba ahmadi	NISOC	Process
Mohammad Reza	Cheraghchi	NISOC	Process
Fazel	Moafi	NISOC	Instrument
Behzad	Zandian	NISOC	Instrument
Peyman	Sarvarian	NISOC	Mechanic
Hojjat	Jafarpour	NISOC	Mechanical
Faride	Parvin	NISOC	Mechanical
Mohammad	Khamisi	NISOC	HSE
Mohammad	Shirali	NISOC	Commissioning
Ali	Hamidan	NISOC	Commissioning
Naji	Hamid	NISOC	Commissioning
Khodadad	Kavosi	NISOC	Commissioning
Reza	Gholgheysari	NISOC	Process Engineer
Mobin	Saeedi	NISOC	Instrument
Mohammad	Bakhshi Mohammadi	Gachsaran NISOC	Production Engineer
Shahram	Valizadeh	Gachsaran NISOC	Production Engineer
Vahid	Mussavi	Gachsaran NISOC	Production Engineer
Mohammad	Fakoor	PEDCO	Process Engineer
Farshid	Amiri	PEDCO	Piping Lead Engineer
Hadi	Mozaffari	PEDCO	Electrical Engineer
Mahdi	Karimi	PEDCO	Head of Electrical Department
Pouria	Bavarsad	PEDCO	Piping Engineering
Sadegh	Gharacheh	PEDCO	Process
Morteza	Taherkhani	PEDCO	Head of I&C
Sepideh	Akbari	PEDCO	I&C Engineer
Sasan	Faramarzpour	PEDCO	Head of Process and Safety Department
Pouya	Maleki	PEDCO	Process Engineer









عمومی و مشترک

شماره پیمان:

 $\bullet \Delta \Upsilon - \bullet V \Upsilon - 91 \Lambda \Upsilon$

	HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION										
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه				
BK	SSGRL	PEDCO	110	GE	RT	0004	D00				

شماره صفحه: 9 از 17

First Name	Last Name	Company	Expertise
Mehdi	Sadeghian	PEDCO	Surface Manager
Vahid	Abdeshadi	PEDCO	Project Engineer Manager
Masoud	Asgharnejad	Hirgan Energy	Engineering Manager
Mohsen	Aryafar	Hirgan Energy	Process
Saeed	Ghanbari	Hirgan Energy	Process
Parisa	Hajisadeghi	Hirgan Energy	Head of I&C
Mohammad	Fakharian	Hirgan Energy	Project Manager
Ali	Baghaei	HAZOP Consultant	Process Safety
Firoozeh	Khosravi	HAZOP Consultant	Process Safety





شماره صفحه: 10 از 17





عمومی و مشترک

شماره پیمان:

 $\bullet \Delta T - \bullet V T - 91 \Lambda F$

	HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION									
پروژه	نسخه سریال نوع مدرک رشته تسهیلات صادر کننده بسته کاری پروژ									
BK	SSGRL	PEDCO	110	GE	RT	0004	D00			

8.1 APPENDIX B – DRAWINGS LIST

Drawing No.	Drawing Title	Place(s) Used
BK-W007S-PEDCO-110-PR-PI- 0001_D01	Extension of Binak B/C Manifold (6 sheets)	Nodes: 1









عمومی و مشترک

شماره پیمان:

 $\bullet \Delta T - \bullet V T - 91 \Lambda F$

HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION										
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه			
BK	SSGRL	PEDCO	110	GE	RT	0004	D00			

شماره صفحه: 11 از 17

8.1 APPENDIX C - NODES LIST

Nodes	Color	Туре	Drawings	Equipment ID	Date
Extension of Binak B/C Manifold	Yellow	Line	BK-W007S-PEDCO-110-PR- PI-0001_D01	-	1. 06/25/2022



عمومی و مشترک







شماره صفحه: 12 از 17



شماره پیمان:

 $\bullet \Delta T - \bullet V T - 91 \Lambda F$

	HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION										
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه				
BK	SSGRL	PEDCO	110	GE	RT	0004	D00				
	· ·				•						

8.1 APPENDIX D - RECOMMENDATIONS LIST

Recommendations	Place(s) Used	Responsibility	Status
6. Recheck size of FCV-1701A~F.	Consequences: 1.1.5.1	Contractor	Open
Relocate class change from LN12 to FN05 at downstream flange of ESDV-1701A.	Consequences: 1.1.4.2	Contractor	Closed
2. Size of ESDV-1701A should be 4".	Consequences: 1.1.4.2	Contractor	Closed
3. Remove DCS solenoid valve on ESDV-1701A.	Consequences: 1.1.4.2	Contractor	Closed
General recommendation: Show on P&ID local HS of all ESDVs.	Consequences: 1.1.4.2	Contractor	Closed
5. Remove cascade level control signal on FIC-1701A.	Consequences: 1.1.5.1	Contractor	Closed
7. Relocate PRV-1701A to upstream of FCV-1701A with class 600#. Also provide procedure that always one manual valve of flow lines to manifolds A/B shall be open.	SIL determination: 1.1.5.1	Contractor	Closed
8. Type of LT-1701 should be changed to float type.	Consequences: 1.6.1.1	Contractor	Closed
9. Remove auto start of oil sump pump P-1701.	Consequences: 1.6.1.1	Contractor	Closed
10. Consider double block for PG-1701A, PG-1702A and inlet side of TRV-1701A.	Consequences: 1.8.1.1	Contractor	Closed
11. Remove connection of oil sump pump to drain header and also duplicated isolation valve and check valve at discharge of this pump.	Consequences: 1.12.1.1	Contractor	Closed
12. Piping class downstream of oil sump pump check valve to header A/B should be 300#.	Consequences: 1.12.1.1	Contractor	Closed
General recommendation: Proxy limit switch signal of ESDVs in BINAK manifold should be routed directly to DCS.	Consequences: 1.12.1.1	Contractor	Closed







شماره صفحه: 13



عمومی و مشترک

شماره پیمان: ۹۱۸۴ – ۰۷۳ – ۰۵۳

از 17		NSION	IFOLD EXTE	C MAN	BINAK B/	PORT FOR	HAZOP RE	
	نسخه	سريال	نوع مدرك	رشته	تسهيلات	صادر کننده	بسته کاری	پروژه
	D00	0004	RT	GE	110	PEDCO	SSGRL	BK

8.1 APPENDIX E – HAZOP WORKSHEETS

Node: 1. Extension of Binak B/C Manifold

Deviation: 1. No/Less Flow

Causes	Consequences	Safeguards	Recommendations
Decreased flow from multiple wellheads due to any reason	No hazardous consequence		
Decreased flow from one wellhead due to any reason (The study is performed for flow line from W018S, the results are applicable for other flow lines)	Slight decreased production with no hazardous consequence for this node	1. FAL-1701A	
3. Upstream flow line rupture	Slight decreased production with no hazardous consequence for this node	1. FAL-1701A	
	Possibility of reverse flow from manifold and	PALL-1701A that will activate ESD	
	and possibility of fire	Wellhead will be closed on flow line pressure loss	
		3. Check valve is considered	
		PALL on other flow lines will close regarding ESDV	
ESDV-1701A closed by failure or error	Slight decreased production	1. FAL-1701A	
	Increased pressure upstream of valve with possibility of damage	Position switch on valve	Relocate class change from LN12 to FN05 at downstream flange of ESDV-1701A.
			2. Size of ESDV-1701A should be 4".
			3. Remove DCS solenoid valve on ESDV-1701A.
			4. General recommendation:Show on P&ID local HS of all ESDVs.
5. FCV-1701A closed more by a failure in any elements of its control loop	Increased pressure upstream of valve with possibility of damage, fire	1. FAL-1701A (dependent)	5. Remove cascade level control signal on FIC-1701A.
	and personnel injury	PAHH-1701A that will activate ESD	6. Recheck size of FCV- 1701A~F.



عمومی و مشترک



شماره پیمان:

 \cdot Δ T - \cdot VT - 9 1 Λ F

HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION								
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه	
BK	SSGRL	PEDCO	110	GE	RT	0004	D00	

شماره صفحه: 14 از 17

Deviation: 2. More Flow

Causes	Consequences	Safeguards	Recommendations
Increased flow/pressure from one wellhead due to any reason (The study is performed for flow line from	Increased flow and pressure in flow line with no hazardous consequence for this node	1. FAH-1701A	
W018S, the results are applicable for other flow lines)	Possible increased level in separator	Level controller and protection in separator	
2. FCV-1701A open more by a failure in any elements of	Possible increased level in separator	Level controller and protection in separator	
its control loop		2. FAH-1701A (dependent)	

Node: 1. Extension of Binak B/C Manifold

Deviation: 3. Reverse/Misdirected Flow

Causes	Consequences	Safeguards	Recommendations
Check valves are considered where required			
2. Rupture of flow line	Possibility of reverse flow from manifold to flow line	Check valve is considered on each flow line	
		2. PAHH-1701A that will activate ESD and closed ESDV-1701A	

Node: 1. Extension of Binak B/C Manifold

Deviation: 4. High Pressure

Causes	Consequences	Safeguards	Recommendations
Line box-in and thermal expansion for each line	Damage to line and loss of containment	1. TRV-1701A	

Node: 1. Extension of Binak B/C Manifold

Deviation: 5. Low Pressure

Causes	Consequences	Safeguards	Recommendations
No new issue was identified			

Node: 1. Extension of Binak B/C Manifold

Deviation: 6. High Level

Causes	Consequences	Safeguards	Recommendations
High level in existing oil sump due to accumulation	Over flow of oil from sump with environmental impact	1. LAH-1701 that will start pump	8. Type of LT-1701 should be changed to float type.
of liquids during maintenance, upset, etc.		Sump size is large compare to inlet flow	9. Remove auto start of oil sump pump P-1701.



عمومي و مشترك







شماره پیمان:

 \cdot Δ T - \cdot VT - 9 1 Λ F

HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION								
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه	
BK	SSGRL	PEDCO	110	GE	RT	0004	D00	
								-

شماره صفحه: 15 از 17

Node: 1. Extension of Binak B/C Manifold

Deviation: 6. High Level

Causes	Consequences	Safeguards	Recommendations
		3. Intermittent operation	

Node: 1. Extension of Binak B/C Manifold

Deviation: 7. Low Level

Causes	Consequences	Safeguards	Recommendations
Pump of existing oil sump remained in service when not required	Possibility of damage to pump	1. LAL-1701 will stop pump	

Node: 1. Extension of Binak B/C Manifold

Deviation: 8. Maintenance Hazards

Causes	Consequences	Safeguards	Recommendations
1. Isolation	Possibility of leakage during maintenance		10. Consider double block for PG-1701A, PG- 1702A and inlet side of TRV-1701A.

Node: 1. Extension of Binak B/C Manifold

Deviation: 9. Leakage

Causes	Consequences	Safeguards	Recommendations
Flange or fitting leakage in flow lines inside fence	Due to low H2S, no severe toxic effect		

Node: 1. Extension of Binak B/C Manifold

Deviation: 10. Corrosion

Causes	Consequences	Safeguards	Recommendations
Corrosion of flow line and		Material of construction (NACE)	
piping due to sulphur	piping with possibility of damage	2. Corrosion monitoring (CP/CC)	

Node: 1. Extension of Binak B/C Manifold

Deviation: 11. Composition

Causes	Consequences	Safeguards	Recommendations
1. Change in GOR	Increased pressure in system	design pressure is based on change in GOR	
2. Increased water cut	Increased corrosion and change in hydraulic	Increased water cut is considered in design	
3. Sand from upstream	Increased erosion of flow	1. Inspection & maintenance	









عمومی و مشترک

شماره پیمان:

 $\cdot \Delta \Upsilon - \cdot V \Upsilon - 91 \Lambda \Upsilon$

HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION								
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه	
BK	SSGRL	PEDCO	110	GE	RT	0004	D00	

شماره صفحه: 16 از 17

Node: 1. Extension of Binak B/C Manifold

Deviation: 11. Composition

Causes	Consequences	Safeguards	Recommendations	
	line and blockage of system	procedures		

Node: 1. Extension of Binak B/C Manifold

Deviation: 12. Miscellaneous

Causes	Consequences	Safeguards	Recommendations
1. See Recommendation			11. Remove connection of oil sump pump to drain header and also duplicated isolation valve and check valve at discharge of this pump.
			12. Piping class downstream of oil sump pump check valve to header A/B should be 300#.
			13. General recommendation: Proxy limit switch signal of ESDVs in BINAK manifold should be routed directly to DCS.





شماره صفحه: 17 از 17





عمومی و مشترک

شماره پیمان:

. 24 - . 14 - 4114

HAZOP REPORT FOR BINAK B/C MANIFOLD EXTENSION								
پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه	
BK	SSGRL	PEDCO	110	GE	RT	0004	D00	
								-

D00

8.1 APPENDIX F - MARKED-UP P&IDS











