

								<b>BINAK OILFIELD DEVELOPMENT</b>	 <b>PARSTABLEAU</b> (P.S.S)  <b>BLUE&amp;P</b> A Subsidiary of BLUE&P Infrastructure Group
<b>DOCUMENT NO.</b>								<b>DOCUMENT TITLE</b> Deviation List	Page <b>1</b> of <b>2</b>
Proj.	Unit	Disc.	PO. NO.	EQ.	Type	Ser. No.	Rev.		

**DOCUMENT TITLE :**

# Deviation List

								<b>BINAK OILFIELD DEVELOPMENT</b>	 
<b>DOCUMENT NO.</b>								<b>DOCUMENT TITLE</b> Deviation List	Page <b>2</b> of <b>2</b>
Proj.	Unit	Disc.	PO. NO.	EQ.	Type	Ser. No.	Rev.		

Item	Deviation
1	Minimum Thickness is 2mm According to the type test obtained.
2	The construction structure of the voltage transformer is tilting
3	In Tech.Offer Rating of Each Capacitor Bank Is 600KVAR
4	
5	
6	
7	
8	
9	
10	