

NISOC

نگهداشت و افزایش تولید میدان نفتی بینک

سطح الارض و ابنيه تحت الارض





شماره صفحه: 1 از 7

خرید بسته نم زدای گاز ایستگاه تقویت فشار گاز بینک

(قرارداد BK-HD-GCS-CO-0010_08)

N2 PURGING PROCEDURE

شماره پیمان:

053 - 073 - 9184

پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه
BK	GCS	MF	120	Q	PR	0014	V00

طرح نگهداشت و افزایش تولید 27 مخزن

N2 PURGING PROCEDURE

نگهداشت و افزایش تولید میدان نفتی بینک

V00	APR. 2025	IFA	MFS	M.Fakharian	S.Faramarzpour	
Rev.	Date	Purpose of Issue/Status	Prepared by:	Checked by:	Approved by:	CLIENT Approval

Status:

IFA: Issued For Approval
IFI: Issued For Information
AFC: Approved For Construction



REVISION RECORD SHEET

PAGE	V00	V01	V02	V03	V04
1	X X X X		 	-	
2	X				
À	Ŷ				
5	X				
7	X				
, 8	^				
a					
10					
11 12					
13					
1/					
15					
16 17			†		
12					
10					
20	-		-	-	
21			†		
23					
2/					
25					
26 27					
28					
20					
30					
31 32					
22					
3/					
35					
26 37					
38					
30					
40					
/11 //2					
13					
11					
45	-		 	1	
16 17	-			-	
10					
10					
50	-				
51 52	1				
53					
51					
<u> </u>	-				
<u>56</u> 57	1				
50					
50					
60					
61 62	-				
63					
6/					
65		l			<u> </u>

PAGE	V00	V01	V02	V03	V04
66					
67					
68					
60 70					
71					
72					
73					
7 <i>1</i> 75					
76					
77					
78					
70			1		
20 21					
82					
83					
8/	-		1		
95 96	1		 		
97					
88					
80					
<u> </u>					
01 02					
03					
0.4					
95					
96 97					
0.0					
aa					
100					
101 102			-		
103					
104					
105					
106					
107 108					
100					
110	ļ				
111	 		1		-
112	1		 		
11/					
115					
116	 	1	1		-
117	1	1	+		1
110 110			1		
120					
121					
122	-		-		
122					
125					
126					
127	<u> </u>				
128	 		1		-
120 130	 	-	 		
7.30	1	1	1	1	1



سطح الارض و ابنيه تحت الارض

نگهداشت و افزایش تولید میدان نفتی بینک







شماره صفحه: 3 از 7

NISOC

خرید بسته نم زدای گاز ایستگاه تقویت فشار گاز بینک

(قرارداد BK-HD-GCS-CO-0010_08)

شماره پیمان:

053 - 073 - 9184

N2 PURGING PROCEDURE

پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه
BK	GCS	MF	120	QC	PR	0014	V00

Contents

1.	SCOPE	4
2.	DEFINITIONS	4
3.	N2- PURGE & EQUIPMENT:	4
4.	REPORTING	6

		ک	CHIRGAN THE						
NISOC	خرید بسته نم زدای گاز ایستگاه تقویت فشار گاز بینک (قرارداد BK-HD-GCS-CO-0010_08)								MES No. con a l Y. 20 £ 3 Ng 1
شماره پیمان:			N2 PUR						
053 - 073 - 9184	پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه	شماره صفحه: 4 از 7
	BK	GCS	MF	120	QC	PR	0014	V00	

1. SCOPE

This procedure covers requirements of Preservation and Long-Term Storage, which will be applied by Masnouat Felezi Sangin Co. National Iranian South Oilfields Company (NISOC).

2. **DEFINITIONS**

CLIENT: National Iranian South Oilfields Company (NISOC)

PROJECT: Binak Oilfield Development – General Facilities

EPD/EPC CONTRACTOR (GC): Petro Iran Development Company (PEDCO)

EPC CONTRACTOR: Joint Venture of: Hirgan Energy – Design &

Inspection(D&I) Companies

VENDOR: MFS Co.

3. N2- PURGE & EQUIPMENT:

After the completion of fabrication process and before dispatching the equipment to site, all equipment internal volume shall be filled by nitrogen gas as it is described below and suitably packed based on project packing specification:

4.1- When the hydrostatic test has been successfully conducted, all equipment shall be drained, dried and cleaned. Afterwards all openings shall be closed hermetically with suitable blinds and gaskets, so that the N2-gas which fills the equipment internal not able to escape from any un-wanted orifice.

		ک	White is the state of the state						
NISOC	خرید بسته نم زدای گاز ایستگاه تقویت فشار گاز بینک (قرارداد BK-HD-GCS-CO-0010_08)								MES Normal National
شماره پیمان:			N2 PUR						
053 - 073 - 9184	پروژه	بسته کاری	صادر کننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه	شماره صفحه: 5 از 7
	BK	GCS	MF	120	QC	PR	0014	V00	

4.2- Before Nitrogen filling equipment inside will be visually checked for any residue dirt, oil residue, metal chips or other forms of contamination, residue water or any contamination,

debris, oil and grease shall be cleaned and remained water shall be dried with compressed air.

- 4.3- All flange connections should be closed and relevant bolts to be tight before purging process. Repairs and rework are not allowed on purged Equipment. If repairs are required the purging must be stopped & started again after finishing repair process.
- 4.4- After all necessary instruments have been checked, the nitrogen gas shall be inserted through one of the bottom nozzles already prepared, the remaining nozzles shall be air tightened except the one upper which will act as the air drainage nozzle.
- 4.5- The purity of nitrogen gas used for purging should be 99 percent.
- 4.6- While nitrogen gas being inserted into the equipment, the remaining air content within the equipment will forcefully be exhausted through the designated drainage nozzle, so, gradually all the air exist within the equipment will be evacuated, to assure a complete air evacuation is to simply release the internal gas from vent hole and light a match in front of the escaping gas, if the light goes off, then no air is trapped inside the equipment, therefore, what is coming out is pure Nitrogen. Drainage nozzle shall be placed at the top point of the vessel.
- 4.7- After all the above procedure is fulfilled, the air drainage nozzle shall be fully tightened to avoid any un-wanted leakage.
- 4.8- After one of the pressure gauges is mounted, fill-in the equipment with cleaned N2-gas the way that filled gas pressure raises to about 0.5 barg, maximum 0.7 barg.
- 4.9- After making sure that equipment internal is completely with N2 gas, feeding entrance shall be tightened and pack as it was mentioned.
- 4.10- As the Nitrogen is normally kept in pressured liquid form in portable capsules, special precautions shall be considered to prevent freezing especially in small diameter branch connections while filling. Visual inspection shall conduct after N2 purge.

<u>₹</u>		ک	المجاهدة الم						
الله بسته نم زدای گاز ایستگاه تقویت فشار گاز بینک NISOC (BK-HD-GCS-CO-0010_08)									MFS No. 2015 No.
شماره پیمان:			N2 PUR						
053 - 073 - 9184	پروژه	بسته کاری	صادركننده	تسهيلات	رشته	نوع مدرك	سريال	نسخه	شماره صفحه: 6 از 7
	BK	GCS	MF	120	QC	PR	0014	V00	

- 4.11- Afterward the equipment is ready for transport to the site.
- 4.12- For Sealing of all flanges, MFS will use Blinds which will be extracted from Plate, with metal gaskets non asbestos and suitable temporary bolt and nuts.
- 4.13- During storage of equipment at site, The Inert gas pressure shall be checked by Owner periodically and as required. If needed it shall be re-pressurized with the same inert gas.

4. REPORTING

After purging, all necessary information shall be reported in Report form which has been mentioned in the next page.



REFERENCE CODE:PR-08-01 REVISION NO:05 REVISION DATE: 2024-05-29	N2 PURGIN	NG REPORT	FORM CODE:FR-08-01/63 REVISION NO.:00 REVISION DATE: 2024-05-29
Project:	OWNER:		Report No:
Reference:	Equipment No.:		DWG NO.:
ITP No:	Report Date:		Page:
Precleaning:		Method of precleanin	g:
Pressure:		Method of purging:	
Pressure Gauge:		Pressure Range:	
Result of Inspection:			
V: C: "ببتعه کامعه"		TPI:	O: